



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III19016022/Fsf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 23-04-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8625C	Veh. Inspected	FW 4593L
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19090163	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	11/04/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VFR800	c.c	782
Engine No.	HIDDEN	Year of Reg.	2003
Chassis No.	JH2RC46C62M404611	Colour	SILVER
Odometer	1096	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55 R17	PIRELLI	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2019	Inspection Date	10/09/2019
Survey held at	25 KAKI BUKIT RD 4 #01-68		
Repairer	MY CAR CONSULTANT PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------