

SMN2SSM.

TP 1st Cap.

Hyundai Avante

Kanchana.

KMH0841CMKU918322

|                                        |                |                               |
|----------------------------------------|----------------|-------------------------------|
| Rear Number Plate                      | new            | 30(SN) x                      |
| Rear Number Plate Holder               | new            | 30(SN) x.                     |
| Rear Number Plate Lamp x 02            | new            | $39.4 \times 2 = 78.80$ 3940  |
| Rear Bumper                            | Deland         | 654.30 ✓                      |
| Rear Bumper Side Holder x 02           | new            | $85.9 \times 2 = 171.80$ ✓    |
| Rear Bumper Lower Garnish              | new            | 496.30 ✓                      |
| Rear Bumper Reinforcement              | new            | 489.30 ✓ 345.                 |
| Rear Bumper Reinforcement Bracket x 05 | 2 piece<br>new | $35 \times 5 = 175$ 70        |
| Rear Bumper Lamp x 02                  | new            | $305.7 \times 2 = 611.40$ 252 |
| Rear Bumper Clips.                     | new            | 30 ✓                          |
| Reverse Sensor                         | Damaged        | <del>280(SN)</del> 200(SN)    |
| Rear End Panel                         | new            | 657.80 x                      |
| Rear End Panel Top Garnish             | new            | 175.90 x                      |
| Rear End Panel Sealant                 | new            | 60(SN) x                      |
| Bootlid                                | new            | 1853 ✓                        |
| Bootlid Lock                           | new            | 145.70 x                      |
| Bootlid Weatherstripe                  | new            | 145.60 x                      |
| Hyundai Logo                           | 2 new          | 68.90 ✓                       |
| Avante Emblem                          | new            | 80.30 ✓                       |

4061. S.N: 200

3248.80

SMN299SM

Panel Beating

~~1000~~ 400

Spray Painting.

~~1000~~ 600

Wiring

~~50~~ 30

To undersend

~~150~~ 50

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~150~~ 60

To transfer bootlid fittings.

~~150~~ 60

1250

total: 4698.80

H/S: 3-7K. ✓

04 Days.