

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412
Singapore 539195
Tel:62898126 Fax :62870590
Company Reg No:200704370C GST Reg No ::200704370C

Your ref : YN3397R

Date:

15/4/2020

not Authorized
Nikh
20/4/20
4/5 2600
to high the Affluence
4 days

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR 8/4/2020

DATE OF ACCIDENT : 15/12/2019

TO SUPPLY :

LIST ITEMS			
01)	1 PC	REAR BUMPER	20/12.1 \$ 601.00
02)	1 PC	REAR BUMPER CLIPS	per \$ 60.00
03)	1 PC	REAR BUMPER LOWER BLACK GARNISH	to 122.00
04)	1 PC	REAR BUMPER REINFORCEMENT	CM \$ 304.00
05)	1 PC	END PANEL	to \$ 282.00
06)	1 PC	END PANEL GARNISH	17 \$ 69.00
07)	1 PC	BOOTLID RUBBER	17 \$ 149.00
08)	1 PC	BOOTLID RUBBER BADGE	to \$ 34.00
09)	1 PC	BOOTLID CERATO EMBLEM	per \$ 39.00
10)	2 PCS	PARKING SENSOR	shaded \$ 428.00
11)	1 PC	BOOTLID FORTE EMBLEM	to \$ 36.00
12)	10 PCS	BOOTLID UPPER LOCK	to \$ 100.00
13)	1 PC	BOOTLID LOWER CATCH	17 \$ 24.00
14)	2 PCS	TAILLAMP	to \$ 388.00
			\$ 2,636.00
		LESS 10%	\$ (263.60)
			\$ 2,372.40
Labour Cost			
15)		SPRAY PAINT	\$ 980.00
16)		LABOUR CHARGE TO RENEW AND REFIX PARTS	\$ 980.00
17)		WIRING	\$ 30.00
18)		TUFF KOTE	\$ 120.00
19)		TO REMOVE AND RENW SENSOR	\$ 60.00
		TOTAL	\$ 4,542.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary page 1 of 2 resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

7-1926
100
7-1715.4
7-1550.0