

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

vic

Address: NO 78, SHENTON WAY, #07-16

S(079120)

Telephone: 64193000

Fax: 68357416

Email shengyang.lim@aig.comnoormarriesa.abukassim@aig.com

Make/ Model : HONDA MOBILO

Date: 13.04.2020

Chassis No : MRHDD4870FP000263

Vehicle No: SKV1821U

Date/Time of Accide 06.04.2020/2300

Date of Reg: 01.09.2015

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	TAILGATE <i>Dented</i>	1	\$ 956.80		\$ ✓ 956.80
2	TAILGATE LOGO <i>new</i>	1	\$ 105.30		\$ + 105.30
3	TAILGATE MOBILO EMBLEM <i>new</i>	1	\$ 98.60		\$ ✓ 98.60
4	TAILGATE I VTEC EMBLEM <i>new</i>	1	\$ 97.30		\$ ✓ 97.30
5	TAILGATE RS EMBLEM	1	\$ 96.80		\$ ✓ 96.80
6	TAILGATE LAMP <i>new RH cracked</i>	2	\$ 202.70		\$ + 405.40 202.70
7	TAILGATE LAMP INNER SEALER <i>new</i>	2	\$ 40.00		\$ + 80.00
8	TAILGATE OUTER GARNISH <i>new could</i>	1	\$ 245.80		\$ ✓ 245.80
9	TAILGATE INNER TRIM <i>could</i>	1	\$ 298.70		\$ ✓ 298.70
10	TAILGATE TOP TRIM <i>new</i>	1	\$ 245.80		\$ + 245.80
11	TAILGATE REAR WIPER COVER <i>new</i>	1	\$ 18.70		\$ + 18.70
12	TAILGATE POCKET HANDLE <i>new</i>	1	\$ 68.90		\$ + 68.90
13	TAILGATE INNER LOCK <i>new</i>	1	\$ 185.20		\$ ✓ 185.20
14	TAILGATE STOPPER <i>new</i>	2	\$ 35.00		\$ + 70.00
15	TAILGATE LOCK CATCH <i>new</i>	1	\$ 45.00		\$ + 45.00
16	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 186.20		\$ ✓ 186.20
17	TAILGATE ABSORBERS <i>new</i>	2	\$ 168.10		\$ + 336.20
18	TAILGATE HINGES <i>new</i>	2	\$ 98.20		\$ + 196.40
19	TAILGATE WINDSCREEN MOLDING <i>new</i>	1	\$ 98.60		\$ ✓ 98.60
20	TAILAMPS <i>could</i>	2	\$ 278.90		\$ ✓ 557.80
21	TAILAMPS INNER SEAL <i>new</i>	2	\$ 40.00		\$ + 80.00
22	REAR BUMPER <i>Dented</i>	1	\$ 586.30		\$ ✓ 586.30
23	REAR BUMPER SIDE RETAINERS <i>new</i>	2	\$ 69.50		\$ ✓ 139.00
24	REAR BUMPER ATTACHMENT RETAINERS <i>new</i>	2	\$ 68.20		\$ + 136.40
25	REAR BUMPER REFLECTORS <i>could</i>	2	\$ 58.10		\$ ✓ 116.20
26	REAR BUMPER SPONGE <i>could</i>	2	\$ 185.20	310	\$ ✓ 185.20
27	REAR BUMPER CHROME GARNISH <i>new</i>	1	\$ 195.60		\$ ✓ 195.60
28	END PANEL <i>Dented</i>	1	\$ 398.70		\$ ✓ 398.70
29	END PANEL TOP GARNISH <i>could</i>	1	\$ 168.40		\$ ✓ 168.40
30	END PANEL ANTENNA SENSOR <i>new</i>	1	\$ 165.20		\$ + 165.20
31	SPARE TYRE PANEL <i>Repair</i>	1	\$ 1,310.70		\$ + 1,310.70

32	SPARE TYRE PANEL TOP INSULATOR <i>new</i>	1	\$ 298.30	\$ <i>+</i> 298.30
33	REAR ALARM SPEAKER <i>new</i>	1	\$ 123.60	\$ <i>+</i> 123.60
34	REAR FENDER INNER TRIMS <i>new</i>	2	\$ 289.50	\$ <i>+</i> 579.00
35	REAR SILENCER BOX <i>new</i>	1	\$ 752.30	\$ <i>+</i> 752.30
36	REAR SILENCER BOX GASKETS <i>new</i>	1	\$ 65.80	\$ <i>+</i> 65.80
37	REAR SILENCER BOX HEAT SHIELD <i>new</i>	1	\$ 145.20	\$ <i>+</i> 145.20
38	SPARE TYRE CARRIER <i>new</i>	1	\$ 195.80	\$ <i>+</i> 195.80
39	SPARE TYRE CARRIER BOLT <i>new</i>	1	\$ 49.20	\$ <i>+</i> 49.20
40	SPARE TYRE CARRIER NUT <i>new</i>	1	\$ 45.80	\$ <i>+</i> 45.80
Total List Price Cost				\$ 10,130.20
				PARTS DISCOUNT 20% \$ 8,104.16

4841.90
3873.52

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00	\$ <i>+</i> 50.00
2	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ <i>+</i> 30.00
3	TAILGATE INNER TRIM CLIPS <i>new</i>	1 SET	\$ 30.00	\$ <i>+</i> 30.00
4	TAILGATE TOP TRIM CLIPS <i>new</i>	1 SET	\$ 30.00	\$ <i>+</i> 30.00
5	TAILGATE INSULATOR CLOTH <i>new</i>	1	\$ 220.00	\$ <i>+</i> 220.00
6	TAILGATE LAMP CLIPS <i>new</i>	2 SET	\$ 30.00	\$ <i>+</i> 60.00
7	TAILGATE OUTER GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ <i>+</i> 30.00
8	TAILAMPS CLIPS <i>new</i>	2 SET	\$ 30.00	\$ <i>+</i> 60.00
9	REVERSE SENSORS <i>new</i>	1 SET	\$ 250.00	\$ <i>+</i> 250.00
10	REVERSE CAMERA <i>new</i>	1 SET	\$ 280.00	\$ <i>+</i> 280.00
11	WINDSCREEN SEALANT <i>new</i>	2	\$ 40.00	\$ <i>+</i> 80.00
12	END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ <i>+</i> 30.00
13	REAR FENDER INNER TRIM CLIPS <i>new</i>	2 SET	\$ 30.00	\$ <i>+</i> 60.00
14	REAR EXHAUST TIP GARNISH <i>new</i>	1	\$ 120.00	\$ <i>+</i> 120.00
Total Special Nett Items				\$ 920.00

380

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS	\$ 2,000.00
	800 800
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,800.00
	800 800
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 60 200.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 50 150.00
TO REMOVE/REFIT / REPLACE REVERSE CAMERA	\$ 50 150.00
LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	\$ 120 150.00
LABOUR TO UNDERCOATING TO AFFECTED AREA	\$ 60 180.00
LABOUR TO REMOVE INTERIOR UPHOLSTERY TO FACILITATE REPAIR JOB	\$ 60 150.00
LABOUR TO REMOVE REAR SILENCER BOX	\$ X 150.00
TO CONDUCT WIRING CHECK ON REAR TAILAMPS	\$ 30 150.00
TO REMOVE/REFIT REPLACE BOOTLID MECHANISM	\$ 80 150.00
Total Others Cost	\$ 1,430.00
GRAND TOTAL	
	\$ 16,280.20

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2110

Adnan Lj
 H/c 14/04/20
 06 days

total: 6363.52

H/S: SK ✓