



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Razmy Bin Ali
C/o: 160 Sin Ming Drive #06-13
Sin Ming AutoCity (S) 575722

Date of report: 26.12.2019
Date of request: 11.11.2019
Date of inspection: 11.11.2019
Date of accident: 06.11.2019
Claim type: Third Party Claim

Report No: AAS/2019/561

Particulars of affected vehicle:

Registration no:	SKE7014H	Odometer:	184544 km
Make/Model:	Volkswagen Scirocco 1.4 TSI (A)	Engine Capacity:	1390 cc
Year of registration:	2010	Engine no:	CAV155325
Colour:	Metallic Blue	Chassis no:	WVWZZZ13ZAV429644

Condition of tires:

Front Left:	6mm	Front Right:	6mm
Make:	Pirelli	Make:	Pirelli
Rear Left:	6mm	Rear Right:	6mm
Make:	Pirelli	Make:	Pirelli

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conduct at M/s. Y2K Audio Design
160 Sin Ming Drive #06-13
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 6,355.10
Revised estimate:	\$ 4,998.44
Recommended reserve:	\$ 4,000.00 (Lump sum)

Estimated normal duration of repairs : 3 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7896

Email: absolute.app.svcs@gmail.com

Vehicle No: SKE7014H

Report No: AAS/2019/561

W/O PREJUDICE

Point of impact

At the RHF portion.

General description of damages

The front bumper, front bumper lower lip, front grille, RH headlamp, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Y2K Audio Design as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$4,998.44

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,000.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 3 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 46 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SKE7014H

Report No: AAS/2019/561

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Front bumper (Scirocco R)	1	Dented/Cracked		\$ 1,845.02	\$ 1,845.02
2	Front bumper grille RH	1	Grazed/Repair		\$ 157.92	-
3	Front bumper lamp RH	1	Serviceable		\$ 122.76	-
4	Front bumper retainer LH/RH	2	RH Cracked	\$ 40.23	\$ 80.46	\$ 40.23
5	Front bumper reinforcement	1	Serviceable		\$ 475.93	-
6	Front grille	1	Grazed/Repair		\$ 364.82	-
7	Headlamp RH	1	Cracked		\$ 971.95	\$ 971.95
8	Headlamp bracket RH	1	Distorted		\$ 86.24	\$ 86.24
List total:					\$ 4,105.10	\$ 2,943.44
1	Front bumper carbon lip	1	Cracked		\$ 1,200.00	\$ 1,200.00
Special nett total:					\$ 1,200.00	\$ 1,200.00
Parts Total:					\$ 5,305.10	\$ 4,143.44
S/N	Labour Description				Repairer's Est	Revised Est
1	To check wirings.				\$ 50.00	\$ 30.00
2	To renew all damaged parts. Reform, repair & re-align all affected area.				\$ 500.00	\$ 375.00
3	To respray all affected areas.				\$ 500.00	\$ 450.00
Labour Total:					\$ 1,050.00	\$ 855.00
Grand Total:					\$ 6,355.10	\$ 4,998.44

The final adjusted lump sum amount is \$4,000.00

Under normal circumstances, the repair should be completed within a reasonable period of 3 working days.

46 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.























