



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005346
INV Date 03/08/2020
Reference CC4/FCI20005146/R1ga3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLR 7968A
Insured Veh. SHC 8076T
Claim No. D20001831MFSH
Policy No. D-20094922MFSH
Accident Date 07/04/2020
Inspection Date 04/06/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20005146/R1ga3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-08-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8076T	Veh. Inspected	SLR 7968A	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20001831MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	13/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR XF 2.0 GTDI	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	SAJAC06N5FPU56737	Colour	WHITE	
Odometer	37785	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45Z R18	PIRELLI	6 mm	
L/H Front Tyre	245/45Z R18	PIRELLI	6 mm	
R/H Rear Tyre	245/45Z R18	PIRELLI	6 mm	
L/H Rear Tyre	245/45Z R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/04/2020	Inspection Date	04/06/2020	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7968A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT S20 (SN)	SCRATCHED	2,179.70	1,961.73
1	BUMPER BRACKET FRT R (SN)	SERVICEABLE	44.20	-
1	JC2Z31443/HEADLAMP R (SN)	NOT NECESSARY	3,101.30	-
			5,325.20	1,961.73
	<u>LABOUR</u>			
	TO REPLACE FRT BUMPER ,HEADLAMP RH ETC.		1,800.00	900.00
	TO SPRAYPAINT & BLEND ON FRT BUMPER ,FRT RH FENDER ,ETC.		1,600.00	800.00
	TO FOCUS HEADLAMP .	NOT NECESSARY	180.00	-
	TO CHECK & WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		540.00	540.00
			4,120.00	2,240.00
GRAND TOTAL			9,445.20	4,201.73
RECOMMENDED COST OF REPAIRS				4,201.73

Report Ref No. CC4/FCI20005146/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 7968A

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

