

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WEARNES

Paul

Up 90010068

3 days

P/P

04/06/2020 @ 1700

Repair before paint

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
45 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 09/04/2020

WIP No. : 17917

Veh.In/Out:

*Tel.No. :

Reg.No. : SLR7968A

Reg.date : 28/08/2017

Mileage : 0

Chassis No: SAJAC06N5FPU56737

Singapore 159103

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, HEADLAMP RH ETC	0	1800.00	0	1,800.00	S	900
800	TO SPRAYPAINT & BLEND ON FRT BUMPER, FRT RH FENDER, ETC	0	1600.00	0	1,600.00	S	800
280	TO FOCUS HEADLAMP	0	180.00	0	180.00	S	X
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	540.00	0	540.00	S	/
	BUMPER COVER FRT S20	1.0 EA	2179.70		2,179.70	S	S20
	BUMPER BRACKET FRT R	1.0 EA	44.20		44.20	S	?
	JC2Z31443/HEADLAMP R	1.0 EA	3101.30		3,101.30	S	X

Gross Total. 9,445.20

Labour Total 4,120.00
Parts Total 5,325.20
Package Total 0.00

Net..... 9,445.20
GST @ 7.0% 661.16
Total..... 10,106.35
Paid..... 0.00
Please Pay.. 10,106.35

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X