

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20005147/KGA3Q2
Date: 23/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100312152
Claimant Vehicle No :	SKG4086J	Insured Vehicle No :	SDU444U
Date of Loss:	10/04/2020	Nature of Claim:	TP
		Claim No:	3603751353SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG4086J	Engine No:	CAXB45147
Make & Model:	VOLKSWAGEN PASSAT, 1.4 TSI DSG 3623A7 (A)	Chassis No:	WVWZZZ3CZDP003366
Reg. Date:	30/08/2012 (Man. Year: 2012)	Odometer:	127035 km
Colour:	Metallic Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,349.86	3,469.55	880.31	20.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	1,030.00	200.00	16.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,579.86	4,499.55	1,080.31	19.36
Approved Total (Overridden) (S\$)		4,050.00		

(S\$)	5,579.86	4,050.00	1,529.86	27.42
+ GST 7.00/7.00% (S\$)	390.59	283.50	107.09	27.42
Nett Amount (S\$)	5,970.45	4,333.50	1,636.95	27.42
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,741.50		

INSPECTION

Date of Assignment: 13/04/2020

Date Inspected: 13/04/2020

Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)
 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,298.88 FL	*1,298.88 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	649.44 FL	*- FL
3	1		*FRONT BUMPER LH SPONGE	Serviceable	142.56 FL	*- FL
4	1		*FRONT BUMPER LH OUTER PDC SENSOR	Dented	186.12 FL	*186.12 FL
5	1		*FRONT BUMPER LH PARKING SENSOR	Serviceable	186.12 FL	*- FL
6	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	29.70 FL	*29.70 FL
7	1		*FRONT BUMPER LH RUNNING LIGHT	Cracked	257.40 FL	*257.40 FL
8	1		*FRONT BUMPER LH RUNNING LIGHT GARNISH	Distorted	174.24 FL	*174.24 FL
9	1		*FRONT BUMPER LH INNER GUIDE	Distorted	23.76 FL	*23.76 FL
10	1		*FRONT LH FENDER	Bent	643.50 FL	*643.50 FL
11	1		*FRONT LH FENDER INNER SHIELD	Distorted	304.92 FL	*304.92 FL
12	1		*FRONT LH FENDER BRACKET	Distorted	69.30 FL	*69.30 FL
13	1		*HEADLAMP LH	Cracked	867.24 FL	*867.24 FL
					Sub Total (\$\$)	4,833.18
					- List Item Discount on L Items 10.00/10.00% (\$\$)	483.32
					Total Parts (\$\$)	4,349.86
						3,855.06
						385.51
						3,469.55

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS ,GRILLE ,LH HEADLAMP ,FRT LH FENDER & REALIGN BONNET THE SAME	New	450.00	400.00
2	PUTTY & RESPRAY FRT BUMPER & LOWER SPOILER ,FRT LH FENDER ,BONNET ,FRT LH DOOR & ALL AFFECTED AREAS	New	750.00	600.00
3	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,230.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >