



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

INV No. NA2002862
INV Date 12/05/2020
Reference NS/INC20005153/Fyf3n2
Code INC4



PROFESSIONAL SERVICE FEE

Vehicle No. SH 7007T
Insured Veh. FBN 1670L
Claim No. MT/1091205-002
Policy No. 5102815542-01
Accident Date 09/04/2020
Inspection Date 09/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

HYN




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20005153/Fyf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 12-05-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBN 1670L	Veh. Inspected	SH 7007T	
Policy No.	5102815542-01	Coverage (\$)	0.00	
Claim No.	MT/1091205-002	Excess (\$)	0.00	
Assign From		Assign Date	09/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID (G4)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU103557111	Colour	BLUE	
Odometer	444330	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	7 mm	
L/H Front Tyre	195/65 R15	DAVANTI	7 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	8 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	8 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	09/04/2020	Inspection Date	09/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7007T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PRIG4 COVER REAR BUMPER	DEFORMED / SCRATCHED	458.60	458.60
10	PRIVC BUMPER PIECE	NECESSARY	22.00	22.00
1	PRIG4 GUARD-REAR BUMPER C	SCRATCHED	552.60	552.60
1	PRIG4 FILLER-REAR BUMPER	DEFORMED	148.40	148.40
	LESS 25% DISCOUNT		-295.40	-295.40
			886.20	886.20
	<u>SPECIAL NETT ITEMS</u>			
1	PRIG4 BUMPER PROTECTOR MA (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
			300.00	300.00
	<u>LABOUR</u>			
	PANEL BEATING.		350.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		300.00	200.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	60.00
			730.00	580.00
	GRAND TOTAL		1,916.20	1,766.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,400.00

Report Ref No. NS/INC20005153/Fyf3n2


PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser
DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. SH 7007T

INSPECTION





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SH 7007T

RE-INSPECTION

