

Our Job Ref No 305392725
Date : 24.04.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr RAM
Vehicle Reg No. SHA6020C CTPL

Fax :
08.04.20


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: QBE --- SLM7451A
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,200.00
Final Lumpsum Repair cost \$1,200.00

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Ram
Date : 27/04/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.04.2020

Time: 18:12:53

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305392725
 REGN NO : SHA6020C
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 20.09.2016
 DATE/TIME IN : 08.04.2020 13:35
 ACCIDENT DATE : 08.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 04-01-0302-2534-G PRIG4Q8 COVER FRONT BUMPE	1	L	499.90	25.00	374.92 cut
0002 04-01-0302-2871-G PRIG4 SUPPORT FRONT BUMPE	1	L	82.30	25.00	61.72 Xun
0003 04-01-0302-2297-G PRIG4 EMBLEM SIDE PANEL (	1	L	86.50	25.00	64.87 wel
SUB-TOTAL :					501.51

JOB NATURE

JOB NATURE	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 20-05 FRT FENDER ADVERTISMENT LOGO LH					100.00 wel
0001 L PANEL BEATING (repair frt fender Lh)			500.00		\$480
0002 23-502 SPRAYPAINT ON AFFECTED AREA			450.00		\$400
0003 17-01 CHECK ALL LIGHTING			50.00		
0004 20-00 TUFF COAT ON AFFECTED PARTS.			50.00		\$30
SUB-TOTAL :					1,150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

9/08/2020 1530
 panesurem@lkkauto.com
 88622772
 2 repairer photo
 AA repair photo

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.: 305392725


CUSTOMER NAME COMFORT TRANSPORTATION PTE LTD 7010045 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO.	SHA6020C	MILEAGE
	MAKE :	TOYOTA	FUEL
	MODEL	PRIUS HYBRID(G4)	DATE/TIME IN
	YR OF MANU.	20.09.2016	TARGET DATE
	CHASSIS CODE	JTDKB3FUX03531011	COMPLETION DATE/TIME:

QBE

Accident Date: 08.04.2020
NATURE: 3P 08.04.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHA6020C LKE

Vehicle No.: SHA6020C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard