

Our Job Ref No 305392726

Date : 23.04.20

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHB4128J CTPL , 08.04.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLU520M
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	
(b) Labour Charges	
<b>Total for Part-By-Part Repair Cost</b>	
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>\$3,500.00</u>
<b>Final Lumpsum Repair cost</b>	<b><u>\$3,500.00</u></b>

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount



Signature : \_\_\_\_\_  
 Name : LIM KWOK ENG  
 Tel : 62148316  
 Fax : 65468156

Signature : \_\_\_\_\_  
 Name : \_\_\_\_\_  
 Date : \_\_\_\_\_

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_



Like

NTM C

COMFORTDELGRO ENGINEERING PTE LTD

Date: 09.04.2020

Time: 11:34:53

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305392726  
REGN NO : SHB4128J  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 29.10.2015  
DATE/TIME IN : 08.04.2020 15:20  
ACCIDENT DATE : 08.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 04-01-0103-2322-A I40V3 BUMPER W LIP & FOG	1	L	1,052.20	20.00	841.76 <del>PEF</del>
0002 04-01-0103-0637-G I40VC BRKT ASSY-FR BPR UP	1	L	22.40	20.00	17.92 <del>NEC</del>
0003 04-01-0103-0639-G I40VC BRACKET-FR BUMPER S	1	L	24.60	20.00	19.68 <del>XUN</del>
0004 04-01-0103-0632-G I40V2 COVER-FR BUMPER SID	1	L	93.60	20.00	74.88 <del>XUN</del>
0005 04-01-0103-2164-G I40V3 GRILLE ASSY-RADIATO	1	L	1,480.00	20.00	1,184.00 <del>SCR</del>
0006 04-01-0103-2175-G I40V3 SYMBOL MARK-H	1	L	39.50	20.00	31.60 <del>NEC</del>
0007 FNPS FRT NO PLATE(S)	1	N	25.00	10.00	22.50 <del>MS</del> <sup>55</sup> -10% $\frac{3,982.10}{}$
0008 FNPS FRT NO PLATE(S) TRIM COVE	1	N	30.00	10.00	27.00 <del>MS</del> <sup>49.50</sup> +Supple: 325.30 $\frac{4,307.40}{}$
0009 04-01-0103-0781-A I40VC LAMP ASSY-HEAD LH#	1	L	1,388.00	20.00	1,110.40 <del>SCR</del> <sup>-20%</sup> $\frac{3,445.92}{}$
S Hf steel Rim Rk - #325.30					
SUB-TOTAL : 3,329.74					<sup>+Nett</sup> 49.50 $\frac{3,495.42}{}$
<b>JOB NATURE</b>					
0000 L	PANEL BEATING (repair Bonnet)		450.00	\$420	
0001 23-502	SPRAYPAINT ON AFFECTED AREA		450.00	\$400	820

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305392726  
 REGN NO : SHB4128J  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 29.10.2015  
 DATE/TIME IN : 08.04.2020 15:2  
 ACCIDENT DATE : 08.04.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 17-01 CHECK ALL LIGHTING	50.00				3,495.42
0003 20-00 TUFF COAT ON AFFECTED PARTS.	50.00		<del>100</del> \$30		
SUB-TOTAL : 1,000.00					820
					80
TOTAL : 4,329.74					900

MVA NAME & SIGNATURE  
 DATE :

SURVEYOR NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO

4,395.42

-20%

3,516.33

*Ram(LKK)*  
*# 9/4/2020 1540*  
*Pereswara@lkkauto.com*  
*aga-seg@lkkphoto*  
*#3,500*  
*(3rd party) days*