

PERFECT WERKZ

Block 25 Kaki Bukit Road 4 #06-51 Synergy@ KB Singapore 417800
HP: 92712214 Fax: (65) 69664526 ROC : 53364512C

09th APRIL 2020

RUS AUTO LEASING PTE LTD
25 KAKI BUKIT ROAD4
06-51 SYNERGY @KB
Singapore 417800

TP ALG.
Cecilia

JSAGYC21S00340039.

Accident date: 09th APRIL 2020
Estimated repair cost for vehicle no: SJZ8518R SUZUKI SX4 1.6 ' 2020 DEC

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet <i>NE MR</i>		\$950.00 X
2	1	Front head lamp -LH <i>Crackd</i>	\$78.20	\$1,120.00 X 438
3	2	Front head lamp lower bracket <i>NE MR</i>		\$156.40 X
4	1	Front bumper <i>Distorted</i>	\$112.00	\$950.00 X 652
5	2	Front bumper side bracket <i>LH Rnd</i>	\$5.00	\$224.00 X 39.
6	10	Front bumper clips <i>MR</i>		\$50.00 X 30.
7	1	Front bumper number plate <i>NE MR</i>		\$50.00 X
8	1	Front bumper reinforcement <i>NE MR</i>		\$484.00 X
9	1	Front bumper <i>lower Spoiler</i> <i>Crackd</i>		\$800.00 X 600(SN)
10	1	Front Bumper Fog lamp-LH <i>NE MR</i>		\$221.00 X
11	1	Front Bumper Fog lamp cover-LH <i>Cr</i>		\$88.00 X 65.
12	1	Front Grille		\$215.00 X
13	1	Front Grille emble logo <i>NE MR</i>	\$5.00	\$56.00 X
14	10	Front Grille clips		\$50.00 X
15	1	Front support panel	\$65.20	\$952.00 X
16	1	Front support panel side bracket <i>Not MR</i>		\$65.20 X
17	1	Front fender-LH <i>Distorted</i>		\$524.00 ✓
18	1	Front fender cowl-LH <i>Not MR</i>		\$112.00 ✓
19	5	Front R/H fender cowl-LH <i>Not MR</i>	\$5.00	\$25.00 ✓
20	1	front Tyre-LH <i>NE MR</i>		\$300.00 X
21	2	front rim -LH <i>NE MR</i>		\$400.00 X

Subtotal :- \$7,117.60

1885 S.N: 600(SN)

1602.25 \$120.00 X

Labour charges

To remove & re-fix cushion

\$120.00 X

Wheel alignment (computer)

\$60.00 30

To Check Wiring System

1640 \$120.00 50

Tuff Kote

\$200.00 60

Towing charges

\$900.00 700

Panel beating

\$800.00 800

Spray painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$2,320.00

Total :- \$9,437.60

3K