

C04/FCI20005161/A993

**CAS GARAGE PTE LTD**  
 (Reg No. 201828067M)  
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

**VEHICLE REPAIR ESTIMATE**

Insurance Company: MS FIRST CAPITAL INSURANCE LIMITED

Address: NO 36, ROBINSON ROAD, #16-01  
 CITY HOUSE, S(068877)

*Cecilia*

Telephone: 65073848 Fax: 65073849

Email [motorclaims@msfirstcapital.com.sg](mailto:motorclaims@msfirstcapital.com.sg)

Make/ Model : HONDA SHUTTLE

Date: 13.04.2020

Chassis No : GK82001784

Vehicle No: SMM7227U

Date/Time of Accide 04.01.2020/ 0730

Date of reg: 24.06.2019

**Materials Cost/ Spare Parts Cost**

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	NETT PRICE \$	FINAL PRICE \$
1	REAR WINDSCREEN MOUDLING <i>new</i>	1	\$ 145.30	\$ <del>x</del> 145.30
2	REAR GATE <i>Repair</i>	1	\$ 1,695.00	\$ <del>x</del> 1,695.00
3	REAR GATE LOGO <i>new</i>	1	\$ 108.00	\$ <del>x</del> 108.00
4	REAR GATE EMBLEM "SHUTTLE" <i>new</i>	1	\$ 97.00	\$ <del>x</del> 97.00
5	REAR GATE LAMP	2	\$ 458.30	\$ <del>x</del> 916.60
6	REAR GATE SMART LOCK ANTENNA	1	\$ 185.60	\$ <del>x</del> 185.60
7	REAR GATE WEATHERSTRIP	1	\$ 175.80	\$ <del>x</del> 175.80
8	REAR GATE INNERLOCK	1	\$ 215.30	\$ <del>x</del> 215.30
9	REAR GATE LOCK LATCH	1	\$ 70.00	\$ <del>x</del> 70.00
10	REAR GATE OUTER MOULDING CHROME	1	\$ 385.60	\$ <del>x</del> 385.60
11	REAR GATE STOPPER	2	\$ 38.00	\$ <del>x</del> 76.00
12	REAR GATE INNER TRIM	1	\$ 397.60	\$ <del>x</del> 397.60
13	REAR BUMPER <i>Delat</i>	1	\$ 856.30	\$ <del>✓</del> 856.30
14	REAR BUMPER SPONGES <i>could RH</i>	2	\$ 165.20	75.20 \$ <del>45.20</del> 30.40
15	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 58.60	\$ <del>x</del> 58.60
16	REAR BUMPER RETAINER RH <i>could</i>	1	\$ 82.60	\$ <del>45.20</del> 82.60
17	REAR BUMPER REFLECTOR RH <i>could</i>	1	\$ 85.00	\$ <del>✓</del> 85.00
18	REAR BUMPER REFLECTOR COVER RH <i>ton</i>	1	\$ 156.20	115 \$ <del>✓</del> 156.20
19	REAR END PANEL <i>2 Repair</i>	1	\$ 698.70	\$ <del>x</del> 698.70
20	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 185.90	\$ <del>x</del> 185.90
21	REAR FENDER INNER COWLING <i>ton</i>	1	\$ 156.20	\$ <del>✓</del> 156.20
22	TAIL LAMP RH <i>new rep</i>	1	\$ 498.70	\$ <del>x</del> 498.70
<b>Total Price Cost</b>				\$ 7,576.40
				PARTS DISC 20% \$ 6,061.12

Rear Fender Air duct RH *could* 1

85.90 ✓

Rear Bumper Lower Bracket RH 1

65.70 ✓

*could*

1484.3

1187.44

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1SET	\$ 50.00	\$ + 50.00
2	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ ✓ 30.00
3	REAR BUMPER REFLECTOR GARNISH CLIP <i>new</i>	1SET	\$ 30.00	\$ + 50.00
4	REAR FENDER INNER COWLING CLIPS	1SET	\$ 30.00	\$ + 100.00
5	REAR WINDSCREEN SEALANT	2	\$ 80.00	\$ + 80.00
6	TAILGATE SEALANT	1 SET	\$ 200.00	\$ + 200.00
7	TAIL LAMP CLIP	1 SET	\$ 50.00	\$ x 50.00
8	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ + 150.00
9	REVERSE SENSOR <i>new</i>	1 SET	\$ 250.00	\$ + 250.00
<b>Total Special Nett Items</b>				<b>\$ 960.00</b>

30

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 1,200.00 <i>450</i>
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,200.00 <i>600</i>
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 50 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 40 150.00
TO APPLY SEALANT AND UNDERCOATING TO THE END PANEL	\$ + 200.00
TO REMOVE/ REFIT WIRING CHECKS ON REAR TAILLAMPS	\$ 30 120.00
TO REMOVE/ REFIT REAR WINDSCREEN	\$ x 150.00
TO CONDUCT WATER LEAKAGE TEST	\$ + 80.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 50 150.00
TO REMOVE/TRANSFER REPLACE TAILGATE MECHANISM	\$ + 150.00
<b>Total Others Cost</b>	\$ 1,200.00
<b>GRAND TOTAL</b>	
	<b>\$ 10,621.12</b>

1170

**CAS GARAGE PTE LTD**  
 UEN 201828067M  
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,  
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan  
 Direct Contact: +65 8782 7171  
 Email: allangoh.cas@gmail.com  
 Fax: +65 6509 9501

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Adm G*  
*2/5 #4/09/20*

*O/S Rep.*

*Total: 2387.44*  
*2/5: 1.9K ✓*