



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005438  
INV Date 06/08/2020  
Reference CC4/FCI20005166/Uga3n2  
Code FCI2



### PROFESSIONAL SERVICE FEE

Vehicle No. FBK 2597A  
Insured Veh. SHA 2826X  
Claim No. D20001808MFSH  
Policy No. D-20094922MFSH  
Accident Date 06/04/2020  
Inspection Date 14/04/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20005166/Uga3n2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-08-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 2826X	<b>Veh. Inspected</b>	FBK 2597A
<b>Policy No.</b>	D-20094922MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20001808MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	Heng Ding Chao	<b>Assign Date</b>	13/04/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	YAMAHA MT-09	<b>c.c</b>	847
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JYARN29K000000298	<b>Colour</b>	BLACK
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	120/70Z R17	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>	180/55Z R17	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR & O/S FRONT PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	06/04/2020	<b>Inspection Date</b>	14/04/2020
<b>Survey held at</b>	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 2597A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BALANCER, WHEEL (20G)	NOT NECESSARY	10.00	-
1	BEARING REAR WHEEL (6204)	NOT NECESSARY	44.00	-
1	BOX REAR (KAPPA) KGR52	SERVICEABLE	481.00	-
1	BRACKET, LICENSE	BENT	31.00	31.00
1	COVER PEDAL SHIFT	NOT NECESSARY	13.00	-
1	CRASH BAR (GIVI)	BENT / CUT	381.00	381.00
1	SET GUARD HANDLE	SERVICEABLE	226.00	-
1	HANDLEBAR	BENT	217.00	217.00
1	METER ASSY	CUT	951.00	951.00
1	MUDGUARD REAR	SERVICEABLE	68.00	-
4	NUT (WINDSCREEN) @\$5.00	NECESSARY	20.00	20.00
1	PEDAL, BRAKE	BENT	66.00	66.00
1	PLATE NUMBER REAR (AFTERMARKET)	BENT	47.00	30.00
2	PLUG, SPEC'L SHAPE @\$2.00	NOT NECESSARY	4.00	-
1	REFLECTOR REAR	SCRATCHED	14.00	14.00
1	RIM REAR ASSY	TO REPAIR SEE LABOUR	825.00	-
2	RIVET @\$2.00	NOT NECESSARY	4.00	-
4	SCREW (VISOR) @\$5.00	NOT NECESSARY	20.00	-
1	SEAL OIL	NOT NECESSARY	8.00	-
1	STAND, MAIN	TO REPAIR SEE LABOUR	240.00	-
1	STAY 1	NOT NECESSARY	56.00	-
1	STAY PLATE	NOT NECESSARY	37.00	-
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	MISSING	20.00	20.00
1	STOPPER, MAIN STAND	NOT NECESSARY	10.00	-
1	TYRE 180/55-17 (BRIDGESTONE) T31 TL	SERVICEABLE	300.00	-
1	VALVE RIM	NOT NECESSARY	14.00	-
1	WINDSHIELD (PUIG) MT09 TRACER	CRACKED	409.00	409.00
	LESS 10% DISCOUNT		-	-213.90
			4,516.00	1,925.10

Report Ref No. CC4/FCI20005166/Uga3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b> LABOUR. INCLUSIVE OF THE REPAIR OF RIM REAR ASSY AND STAND, MAIN.		828.00	350.00
			828.00	350.00
	<b>GRAND TOTAL</b>		<b>5,344.00</b>	<b>2,275.10</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,800.00</b>

Report Ref No. CC4/FCI20005166/Uga3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. FBK 2597A

### INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBK 2597A

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

