



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD  
06 RAFFLES QUAY #21-00  
SINGAPORE 048580

FIRST CAPITAL INSURANCE LTD

VEHICLE NO. : FBK2597A  
MAKE/MODEL : YAM / MT-09

NO. : 35953

DATE : 08/04/2020  
CLAIM NO. : 11540  
POLICY NO. : MC/00637057

FROM : HASRIANAH

*Not Allend  
order  
14/4/20  
2/5  
To highlight the  
copy*

(Page 1 of 2)

| S/N | Description                                   | Action         | Qty   | Unit Price | Amount   |
|-----|-----------------------------------------------|----------------|-------|------------|----------|
| 1   | BALANCER, WHEEL (20G)<br>P/N: 65143           | REPLACE        | 1.00  | \$10.00    | 10.00 X  |
| 2   | BEARING REAR WHEEL (6204)<br>P/N: 38880       | REPLACE        | 1.00  | \$44.00    | 44.00 X  |
| 3   | BOX REAR (KAPPA) KGR52<br>P/N: 60855          | REPLACE        | 1.00  | \$481.00   | 481.00 X |
| 4   | BRACKET, LICENSE                              | REPLACE        | 1.00  | \$31.00    | 31.00    |
| 5   | COVER PEDAL SHIFT<br>P/N: 50524               | REPLACE        | 1.00  | \$13.00    | 13.00 ?  |
| 6   | CRASH BAR (GIVI)<br>P/N: 58427                | REPLACE        | 1.00  | \$381.00   | 381.00   |
| 7   | GUARD HANDLE SET                              | REPLACE        | 1.00  | \$226.00   | 226.00   |
| 8   | HANDLEBAR<br>P/N: 51072                       | REPLACE        | 1.00  | \$217.00   | 217.00 ? |
| 9   | LABOUR<br>P/N: 06766                          | Supply/Install | 12.00 | \$69.00    | 828.00   |
| 10  | METER ASSY<br>P/N: 51071                      | REPLACE        | 1.00  | \$951.00   | 951.00   |
| 11  | MUDGUARD REAR<br>P/N: 64913                   | REPLACE        | 1.00  | \$68.00    | 68.00    |
| 12  | NUT (WINDSCREEN)<br>P/N: 46834                | REPLACE        | 4.00  | \$5.00     | 20.00    |
| 13  | PEDAL, BRAKE<br>P/N: 63032                    | REPLACE        | 1.00  | \$66.00    | 66.00    |
| 14  | PLATE NUMBER REAR (AFTERMARKET)<br>P/N: 62696 | REPLACE        | 1.00  | \$47.00    | 47.00 30 |

\*35953 \*

bizSAFE<sub>3</sub>



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383  
ISO 9001: 2015

| S/N | Description                                                  | Action  | Qty  | Unit Price | Amount       |
|-----|--------------------------------------------------------------|---------|------|------------|--------------|
| 15  | PLUG, SPEC'L SHAPE<br>P/N: 65576                             | REPLACE | 2.00 | \$2.00     | 4.00 ?       |
| 16  | REFLECTOR REAR<br>P/N: 57522                                 | REPLACE | 1.00 | \$14.00    | scn 14.00 ✓  |
| 17  | RIM REAR ASSY                                                | REPLACE | 1.00 | \$825.00   | n 825.00 X   |
| 18  | RIVET<br>P/N: 58435                                          | REPLACE | 2.00 | \$2.00     | n 4.00 X     |
| 19  | SCREW (VISOR)<br>P/N: 20898                                  | REPLACE | 4.00 | \$5.00     | 20.00 ?      |
| 20  | SEAL OIL<br>P/N: 65151                                       | REPLACE | 1.00 | \$8.00     | 8.00 ?       |
| 21  | STAND, MAIN<br>P/N: 65152                                    | REPLACE | 1.00 | \$240.00   | n 240.00 X   |
| 22  | STAY 1<br>P/N: 64465                                         | REPLACE | 1.00 | \$56.00    | 56.00 ?      |
| 23  | STAY PLATE<br>P/N: 51046                                     | REPLACE | 1.00 | \$37.00    | 37.00 ?      |
| 24  | STICKER NUMBER PLATE FRONT (BLACK)<br>STRAIGHT<br>P/N: 32921 | REPLACE | 1.00 | \$20.00    | m.s 20.00 ✓  |
| 25  | STOPPER, MAIN STAND                                          | REPLACE | 1.00 | \$10.00    | n 10.00 X    |
| 26  | TYRE 180/55-17 (BRIDGESTONE) T31 TL<br>P/N: 59538            | REPLACE | 1.00 | \$300.00   | scn 300.00 X |
| 27  | VALVE RIM<br>P/N: 27762                                      | REPLACE | 1.00 | \$14.00    | n 14.00 X    |
| 28  | WINDSHIELD(PUIG) MT09 TRACER<br>P/N: 62959                   | REPLACE | 1.00 | \$409.00   | one 409.00 ✓ |

SUB TOTAL

\$5,344.00

GST @ 7 %

\$374.08

GRAND TOTAL

\$5,718.08

**50% deposit required before ordering of parts.**

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

LKK Auto Consultants hence notify  
the Repairer of the following:

Acknowledge &amp; Accepted By

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Acknowledged by Repairer

Signature:

Date:

\*35953 \*

bizSAFE<sub>3</sub>

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2012-1-0363  
ISO 9001: 2015