

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/Fc120005166/43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FSK 2597A

at Workshop m/s

SHH

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

1Yk.

IDAC Accident Rport:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 2263

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FSK 2597A

Yr Regn:

615

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kamoha

MT-09 c.c

847

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

no key

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JYARN29K00000298

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70 ZR17

R:

180/55 ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

614/20

D.O.I.

14/4/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & O/S Rd.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/6/20 Confirmed LTA & 18W with Raymond.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

FIRST CAPITAL INSURANCE LTD

VEHICLE NO. : FBK2597A
MAKE/MODEL : YAM / MT-09

NO. : 35953

DATE : 08/04/2020
CLAIM NO. : 11540
POLICY NO. : MC/00637057

FROM : HASRIANAH

Not Allred
14/4/20
2/5 #1800
3 days 4 days
copy

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER, WHEEL (20G) P/N: 65143	REPLACE	1.00	\$10.00	10.00 X
2	BEARING REAR WHEEL (6204) P/N: 38880	REPLACE	1.00	\$44.00	44.00 X
3	BOX REAR (KAPPA) KGR52 P/N: 60855	REPLACE	1.00	\$481.00	481.00 X
4	BRACKET, LICENSE	REPLACE	1.00	\$31.00	31.00
5	COVER PEDAL SHIFT P/N: 50524	REPLACE	1.00	\$13.00	13.00 X
6	CRASH BAR (GIVI) P/N: 58427	REPLACE	1.00	\$381.00	381.00
7	GUARD HANDLE SET	REPLACE	1.00	\$226.00	226.00 X
8	HANDLEBAR P/N: 51072	REPLACE	1.00	\$217.00	217.00
9	LABOUR P/N: 06766	Supply/Install	12.00	\$69.00	828.00
10	METER ASSY P/N: 51071	REPLACE	1.00	\$951.00	951.00
11	MUDGUARD REAR P/N: 64913	REPLACE	1.00	\$68.00	68.00 X
12	NUT (WINDSCREEN) P/N: 46834	REPLACE	4.00	\$5.00	20.00
13	PEDAL, BRAKE P/N: 63032	REPLACE	1.00	\$66.00	66.00
14	PLATE NUMBER REAR (AFTERMARKET) P/N: 62696	REPLACE	1.00	\$47.00	47.00 30

*35953 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
15	PLUG, SPEC'L SHAPE P/N: 65576	REPLACE	2.00	\$2.00	17 4.00 X
16	REFLECTOR REAR P/N: 57522	REPLACE	1.00	\$14.00	SCN 14.00 ✓
17	RIM REAR ASSY	REPLACE	1.00	\$825.00	12 825.00 X
18	RIVET P/N: 58435	REPLACE	2.00	\$2.00	17 4.00 X
19	SCREW (VISOR) P/N: 20898	REPLACE	4.00	\$5.00	17 20.00 X
20	SEAL OIL P/N: 65151	REPLACE	1.00	\$8.00	17 8.00 X
21	STAND, MAIN P/N: 65152	REPLACE	1.00	\$240.00	12 240.00 X
22	STAY 1 P/N: 64465	REPLACE	1.00	\$56.00	17 56.00 X
23	STAY PLATE P/N: 51046	REPLACE	1.00	\$37.00	17 37.00 X
24	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	* REPLACE	1.00	\$20.00	M.S 20.00 ✓
25	STOPPER, MAIN STAND	REPLACE	1.00	\$10.00	17 10.00 X
26	TYRE 180/55-17 (BRIDGESTONE) T31 TL P/N: 59538	REPLACE	1.00	\$300.00	SCN 300.00 X
27	VALVE RIM P/N: 27762	REPLACE	1.00	\$14.00	17 14.00 X
28	WINDSHIELD(PUIG) MT09 TRACER P/N: 62959	REPLACE	1.00	\$409.00	SCN 409.00 ✓
SUB TOTAL					\$5,344.00
GST @ 7 %					\$374.08
GRAND TOTAL					\$5,718.08

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD**HASRIANAH**

LKK Auto Consultants hence notify

the Repairer of the following:

Acknowledge & Accepted By

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

P-2289
102
P 1880.1
2280.1
P24.

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Acknowledged by Repairer

Signature:

Date:

*35953 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 1, 2002-1-0363
ISO 9001: 2015



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

ATTN: FIRST CAPITAL INSURANCE LTD

NO. : 35953

- Rev. 1

DATE : 08/04/2020
CLAIM NO. : 11540
POLICY NO. : MC/00637057

FROM : HASRIANAH

VEHICLE NO. : FBK2597A
MAKE/MODEL : YAM / MT-09

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET, LICENSE	REPLACE	1.00	\$31.00	27.90
				Disc %: 10.00	
2	CRASH BAR (GIVI) P/N: 58427	REPLACE	1.00	\$381.00	342.90
				Disc %: 10.00	
3	HANDLEBAR P/N: 51072	REPLACE	1.00	\$217.00	195.30
				Disc %: 10.00	
4	LABOUR P/N: 06766	Supply/Install	1.00	\$350.00	350.00
5	METER ASSY P/N: 51071	REPLACE	1.00	\$951.00	855.90
				Disc %: 10.00	
6	NUT (WINDSCREEN) P/N: 46834	REPLACE	4.00	\$5.00	18.00
				Disc %: 10.00	
7	PEDAL, BRAKE P/N: 63032	REPLACE	1.00	\$66.00	59.40
				Disc %: 10.00	
8	PLATE NUMBER REAR (AFTERMARKET) P/N: 62696	REPLACE	1.00	\$30.00	30.00
9	REFLECTOR REAR P/N: 57522	REPLACE	1.00	\$14.00	12.60
				Disc %: 10.00	
10	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$20.00	20.00
11	WINDSHIELD(PUIG) MT09 TRACER P/N: 62959	REPLACE	1.00	\$409.00	368.10
				Disc %: 10.00	

SUB TOTAL

\$2,280.10

GST @ 7 %

\$159.61

GRAND TOTAL (SGD)

\$2,439.71

*35953 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001 2:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*35953 *

bizSAFE₃

