

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SMP 5459P*Not Authorised
Personnel Byprint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

13 APR 2020

SMP 5459P

JTDKB3FU003083717

TOYOTA

PRIUS

6.4.2020

III

30/9/2019

PART

- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 TAPE, BLACK OUT, NO.1 FRT RH
- 1 TAPE, BLACK OUT, NO.2 FRT RH
- 1 TAPE, BLACK OUT, NO.3 FRT RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH
- 1 MOULDING ASSY, BODY ROCKER PANEL, RH

LIST

| | | | |
|-----------------|-----------|-----------------|---|
| \$ | <i>n</i> | 1,300.70 | X |
| \$ | <i>nn</i> | 13.30 | X |
| \$ | <i>nn</i> | 43.50 | X |
| \$ | <i>nn</i> | 26.30 | X |
| \$ | <i>cm</i> | 1,436.60 | ✓ |
| \$ | <i>n</i> | 594.80 | X |
| TOTAL \$ | | 3,415.20 | |
| 25% \$ | | 853.80 | |
| \$ | | 2,561.40 | |

Special Nett

- 1 FRONT WHEEL RIM
- 1 FRONT WHEEL RIM COVER
- 1 FRONT TYRE 195/65/15
- 1SET ROCKER PANEL MOULDING CLIP

| | | | |
|-----------------|-----------|-----------------|---|
| \$ | <i>sn</i> | 1,879.40 | X |
| \$ | <i>sn</i> | 211.50 | X |
| \$ | <i>sn</i> | 350.00 | X |
| \$ | <i>nn</i> | 35.00 | X |
| TOTAL \$ | | 2,475.90 | |

TOTAL PARTS \$ 5,037.30**LABOUR**

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign The
Same

\$ 6,000.00 *del*

Labour charge to mount and dismount vehicle on jig bench, to
facilitate repair.

\$ *nn* 380.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP 5459P

| | | | |
|-------------------------------------------------------------------------------------------------|-----------|------------------|-----|
| Putty And Spray Painting Of The Affected Portion. | \$ | 6,000.00 | 601 |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | nn 380.00 | X |
| To transfer of tire, rim and on wheel balancing. | \$ | nn 170.00 | X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | 201 |
| To Rust-Proofing Of The Affected Areas. | \$ | nn 170.00 | X |
| To transfer of door fittings, attachments and perform water seepage test. | \$ | nn 170.00 | X |
| TOTAL | \$ | 13,660.00 | |
| Over All Total | \$ | 18,697.30 | |

(PART-BY-PART) Repair Days~~20 days~~

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: