



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7282G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	IONIQVC COVER - RR BUMPER	CUT	459.40	459.40
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	IONIQVC BRACKET ASSY - RR B	NECESSARY	55.80	55.80
1	IONIQV2 MOULDING ASSY - RR	SCRATCHED	451.25	451.25
1	IONIQVC REFLECTOR / REFLEX	NOT NECESSARY	31.90	-
1	IONIQV 1-3 LAMP ASSY - REAR	CRACKED	794.40	794.40
1	IONIQV 1-3 LAMP ASSY - REAR	CRACKED	870.40	870.40
1	IONIQ EMBLEM - HYBRID	NECESSARY	24.30	24.30
1	IONIQ EMBLEM - IONIQ	NECESSARY	31.30	31.30
	LESS 20% DISCOUNT		-545.15	-541.77
			2,195.60	2,167.08
<b><u>NETT ITEMS</u></b>				
1	(I40 / SONATA) REAR BOOT LOG (N)	NECESSARY	20.00	20.00
1	(I40 / SONATA) REAR BOOT TEL (N)	NECESSARY	10.00	10.00
	LESS 10% DISCOUNT		-3.00	-3.00
			27.00	27.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	IONIQVC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
1	HYUNDAI REVERSE SENSOR AS (SN)	NOT NECESSARY	135.70	-
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
			385.70	250.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. (REPAIR FENDER LH / BOOT)		700.00	640.00
	SPRAY PAINT ON AFFECTED AREA.		650.00	400.00
	CHECK ALL LIGHTING.		50.00	50.00
	TUFF COAT ON AFFECTED AREAS.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	60.00
			1,530.00	1,180.00

Report Ref No. NS/INC20005179/Fqf3s2



GRAND TOTAL		4,138.30	3,624.08
RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,624.08

Report Ref No. NS/INC20005179/Fqf3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.