

NS/INC 2000 5180/Fr f3

ASSIGNMENT

Estimated Cost

Q1. TP. WB. TP. RES. / QD. RES. / EVA. / RV. / MV.

To inspect Vehicle No.

at Workshop No.

of

Insured

Policy No.

Claim No.

Sum Insured

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Ins No: SHOSITRE

Tr Reg: 01/03/2016

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Private Mover

Truck / Trailer or

Make: Hyundai i 40

cc 1695

Colour: Blue

AD: Insured / Std / NI / NA

Sp Reading: 593 710

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHL841UMQU085464

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 09/04/2020

D.O.I. 13/04/2020

Survey held at comfortd/su (Loyang)

Das. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

NTUC

LS

LS \$1000/- with 2 repair days (Red 109.10, 56%)

confirm on 20/4/2020 with Larry

Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

Transportation

S - RS \$

Phone

Other

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Insp (\$

☐ : Weekend (\$

2/4 - typist

LS \$1000/-

at Formset:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD3178K

DATE: 13. Apr. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 9. Apr. 2020

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>DEF</i>			\$553.00
10	Rear Bumper Clips <i>wcc</i>		\$2.20	\$22.00
1	Rear Bumper Sponge <i>nn</i>			\$103.50
1	Rear Bumper Reinforcement <i>xxm</i>			\$428.40
2	Rear Bumper Reinforcement Brackets LH/RH <i>xxm</i>		\$80.30	\$160.60
1	Rear Bumper Undercover <i>xxm</i>			\$228.00
SUB TOTAL				\$1,495.50
LESS 20%				\$299.10
DISCOUNTED TOTAL				\$1,196.40
1	Rear Bumper Rubber Mat <i>wcc</i>			\$50.00
1	Reverse Sensor <i>xxm</i>			\$135.70
2	Advertisement - Rear Fenders - RH/LH <i>wcc</i>		\$100.00	\$200.00
				\$385.70
Labour Charge				
1	Panel Beating			\$300.00
1	Spray Painting Charge			\$250.00
1	Wiring Charge			\$60.00
1	Remove/refix Reverse Sensor			\$100.00
TOTAL LABOUR				\$710.00
ESTIMATE TOTAL				\$2,292.10

Nett
Nett
Nett

Ram (LKK)

1525 13/04/2020

Paraguru @ account - 6

2862778

2A repair photo

L/S

2 repair by S

\$280
\$200
\$60

Larry Ng

LKK Auto Consultants hence notify
the Repairer of the estimate based on a visual inspection of the above vehicle. The final repair quantum will
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2 repair by S

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305393131
Date : 16. Apr. 2020

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHD3178K

Date of Accident: 9. Apr. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC GBJ821X

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$1,000.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature: [Signature]

Name: Larry Ng

Tel: 6214 8316

Fax: 6546 8156

Signature: [Signature]

Name: RAM

Date: 20/4/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

553.00	50.00	280.00	460.00
22.00	200.00	200.00	250.00
575.00	250.00	60.00	540.00
20%		540.00	1250.00
460.00			20%
			1000.00