



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2002750  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSE  
SINGAPORE 189556

INV Date 27/04/2020  
Reference NS/INC20005180/Fvf3n2  
Code INC4



### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 3178K  
Insured Veh. GBJ 821X  
Claim No. MT/1091287-002  
Policy No. 5106116371-01  
Accident Date 09/04/2020  
Inspection Date 13/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

*HYN*




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20005180/Fvf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 27-04-2020	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBJ 821X	Veh. Inspected	SHD 3178K	
Policy No.	5106116371-01	Coverage (\$)	0.00	
Claim No.	MT/1091287-002	Excess (\$)	0.00	
Assign From		Assign Date	13/04/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU085464	Colour	BLUE	
Odometer	593710	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	6 mm	
L/H Front Tyre	205/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	09/04/2020	Inspection Date	13/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR: <b>2 Working Days</b>			

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3178K**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	553.00	553.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	NOT NECESSARY	103.50	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
2	REAR BUMPER REINFORCEMENT BRACKETS LH/RH @\$80.30	NOT NECESSARY	160.60	-
1	REAR BUMPER UNDER COVER	NOT NECESSARY	228.00	-
	LESS 20% DISCOUNT		-299.10	-115.00
			1,196.40	460.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
2	ADVERTISEMENT-REAR FENDERS-RH/LH @\$100.00 (SN)	NECESSARY	200.00	200.00
			385.70	250.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		300.00	280.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		100.00	60.00
			710.00	540.00
<b>GRAND TOTAL</b>			<b>2,292.10</b>	<b>1,250.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,000.00</b>

Report Ref No. NS/INC20005180/Fvf3n2


**PARASURAM S/O SHANMUGAM**

Asst. Automotive Assessor


**K.K.LAU CPT(RET)**
**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**
**REGD Auto Consultant-SAE, Licensed Appraiser**
**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

### PHOTOGRAPHS FOR VEHICLE NO. SHD 3178K

### INSPECTION







## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H







## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHD 3178K

RE-INSPECTION

