

TRANS-CAB AUTO SERVCIES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7855Z - AXA**Francis***Not Authorised
1/1/14*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7855Z - Francis

LK1LA69RJBB108008*

CHEVROLET

CHEVROLET EPICA 2.0

05.04.2014

AXA**PART****LIST**

1	1	Front Bumper	\$	<i>Beind</i> 1,202.00 ✓
2	1	Front Bumper Retainer RH	\$	<i>Dis</i> 102.00 ✓
3	1	Front Fender RH	\$	<i>R</i> 837.60 ✓
4	1	Front Fender Liner RH	\$	<i>D.1</i> 47.00 ✓
5	1	Front Headlamp RH	\$	<i>mg D.1</i> 816.00 ✓
6	1	Front Shock Absorber Assy RH	\$	216.17 ?
7	1	Front Lower Arm RH	\$	283.00 ?
8	1	Front Knuckle Arm RH	\$	230.00 ?
9	1	Steering Rack End (Spring A-Clock)	\$	88.56 ?
10	1	Front Door RH	\$	<i>R</i> 1,133.00 ✓
11	1	Front Side View Mirror RH	\$	<i>Sn</i> 939.00 X
12	1	Front Side View Mirror Glass RH	\$	<i>Sn</i> 63.00 X
13	1	Front Side View Mirror Signal RH	\$	<i>Sn</i> 189.00 X
14	1	Side Rocker Panel Garnish RH	\$	<i>R</i> 236.40 X
15	1	Rear Door RH	\$	<i>R</i> 1,133.00 ✓
16	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X
17	1	Rear Fender Inner Cowling RH	\$	<i>Sn</i> 76.60 X
18	1	Rear Bumper (Bumper A-RR)	\$	<i>Be</i> 1,202.00 ✓
19	1	Rear Bumper Side Retainer RH	\$	<i>D.1</i> 68.76 ✓
20	1	Rear Bumper Reflectors RH	\$	<i>Sn</i> 119.74 X

TOTAL	\$	10,127.83
10%	\$	1,012.78
	\$	9,115.05

Specical Nett

1set	Front Fender Liner Clip	\$	<i>nn</i> 30.00 X
1Set	Rear Fender Inner Cowling Clip	\$	<i>nn</i> 30.00 ✓
2Set	Front and Rear Bumper Fastener Clip	\$	<i>nn</i> 24.00 ✓
1	Door Sticker "6555-3333"	\$	<i>nn</i> 80.00 <i>cash</i>
1	Door Sticker "Trans-cab"	\$	<i>nn</i> 80.00 <i>cash</i>
2	Rear Windscreen Sealant	\$	<i>nn</i> 100.00 X

TRANS-CAB AUTO SERVCIES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7855Z - AXA**Francis**

1	Rear Windscreen Inner Sponge Seal	\$	100.00	X
1	Rear windscreen inner top garnish	\$	80.00	X
1	Rear Tyre RH	\$	180.00	X
1	Rear Tyre Rim RH	\$	126.00	X
3	Tyre hub cap RH	\$	120.00	X
1	Front Tyre RH	\$	180.00	?
1	Front Tyre Rim RH	\$	126.00	?
1	Front Tyre LH	\$	180.00	?
1	Front Tyre Rim LH	\$	126.00	?
1set	Side Rocker Panel Garnish Clip RH	\$	30.00	X

TOTAL	\$	1,592.00
--------------	-----------	-----------------

TOTAL PARTS	\$	10,707.05
--------------------	-----------	------------------

To Rust-Proofing Of The Affected Areas.	\$	220.00	90%
Putty and Spray Painting Of The Affected Portion.	\$	2,700.00	100%
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	60%
To Check Electrical Lighting Concerned.	\$	170.00	20%
To transfer of tire, rim and on wheel balancing.	\$	170.00	20%
To check steering geometry and computer wheel alignment	\$	220.00	60%
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?
To Remove And Refit Rear W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	120%

TRANS-CAB AUTO SERVCIES PTE LTD**Francis**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7855Z - AXA

*To dismantle and refit rear seat, backrest,
trimings, garnish, roof-lining, speaker
shelfboard, carpeting and other to enable
body work repair.*

\$ *nn* 380.00 *X*

Towing fees

\$ *nn* 120.00 *X*

*To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.*

\$ *nn* 330.00 *X***TOTAL** \$ 7,830.00**Over All Total** \$ 18,537.05**REPAIR DAYS**~~**10 DAYS**~~*5 days*