

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

25-05-20

Date Of Accident : 09-04-2020

OUR REF : SJW 2726L/T/20

Lee Kok Meng

Blk 415C Fernvale Link

#06-70

Singapore 793415

HKIC - Marcus

Date In/out: 11/04/20 to 23/04/20

not Authorized
LKR
14/4/20
2/5 7300/
Take up the repair
9 days

ESTIMATE BILL ON VEH. NO. : SJW 2726L

MODEL : HYUNDAI VELOSTER

CHASSIS NO. : KMTC61DVCU081356

LIST ITEM

Rear Bumper Fascia		DIS 570.50
Rear Bumper Side Retainer		CNE 34.20
Rear Bumper Reinforcement		CNE 437.40
Rear Bumper Reinforcement Bracket - RH		Best 76.80
Rear Bumper Lower Diffuser		Toon 234.50
Rear Bumper Lower Diffuser Chrome Pipe		11 187.50 X
Rear Bumper Clips	10pcs @ 4.50	ner 45.00
Rear Bumper Lower Bracket - RH		15 29.30 X
Rear Bumper Top Bracket - RH		CNE 31.20
Rear Bumper Parking Sensor - RH		CNE 193.60
Rear Bumper Parking Sensor Holder	4pcs @ 51.40	11 205.60 X
Rear Bumper Reflector - RH		320 110.70
Rear Number Plate Lamp	2pcs @ 62.10	11 124.20 X
Rear Bumper Reflector Wire Harness		Toon 191.80
Tail Lamp - RH	950.50	320 1,108.50
Tail Lamp Base Panel		11 298.10 X
Tail Lamp Clips	2pcs @ 4.50	11 9.00 X

Rear Fender - RH	1805.20	Bol/gm/Buc	1,963.90	
Rear Fender Glass Moulding		11	209.50	X
Rear Fender Glass Clips	6pcs @ 4.50	11	27.00	X
Rear Fender Inner Glass Seal		neu	39.10	
Rear Fender Air Vent		CNo	29.10	
Rear Fender Inner Trim Board		De/cra	398.40	
Rear Fender Inner Trim Board Clips	10pcs @ 4.50	11	45.00	X
Rear End Panel		Bol/gm	499.30	
Rear End Panel Top Trim		Toft	143.10	
SET Rear End Panel Top Trim Clips	14pcs @ 4.50	11	18.00	X
Rear Mudflap - RH		Toft	21.40	
Tail Gate	1283.42	Bent/woped	1,479.30	
Tail Gate Weather Stripe		11	91.80	X
Tail Gate Emblum "Veloster"		neu	31.80	
Tail Gate Glass Moulding		neu	49.10	
Tail Gate Inner Seal		neu	39.10	
Tail Gate Clips	14pcs @ 4.50	11	63.00	X
Rear Axle Beam		11	1,499.70	X
Rear Wheel Bearing Hup - RH		Damge	394.90	
Sport Rim Assy		R	1,091.50	X
			12,021.90	
		Less Discount 20%:	2,404.38	
			9,617.52	

p. 7610.12
202
6088.57

SPECIAL NETT ITEM

Rear Number Plate (Chrome)	11	60.00	X
Rear Number Plate Casing	11	29.00	X
Rear Fender Glass Sealant	neu	60.00	30
Tail Gate Glass Sealant	neu	60.00	40
Tyre Assy	su	220.00	X

LABOUR CHARGE

To Check Wiring System.	80.00	30
To Remove & Refix Interior Upholstery.	120.00	80
To Tuff Coat Affected Areas.	180.00	90
To Remove & Transfer Tail Gate Mechanism.	200.00	60
To Remove & Refix Rear Axle Beam. <i>rear undercarriage</i>	380.00	120
To Check and Adjust Computer 4 Wheel Alignment (Before & After).	240.00	80
To Remove & Refix Rear Windscreen Glass (Top & Bottom), Rear RH Fender Glass.	280.00	120
To Respray Affected Areas.	1,350.00	1000
To Renew Damaged Parts, Straighten & Repair Rear Floor Panel, Rear Chassis Member & Aligned All Parts.	1,500.00	1400
To Remove & Refix Sport Rim & Contact Wheel Balancing.	120.00	X
To Remove & Refix Exhaust Silencer.	120.00	X

\$14,616.52	14,736.52	280
GST 7%:	1,031.56	
TOTAL AMOUNT:	15,768.08	

9138.09
7310.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: