

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Chhia Nyuk Pui	Date:	03 Jun 2020

**Preliminary Advice**

Insured Vehicle No	: SLU2654Y	TP Vehicle No	: SJW2726L	Accident Date	: 09/04/2020
Make	: HYUNDAI VELOSTER FS	Date of Inspection	: 14/04/2020	Assignment Date	: 13/04/2020
Inspection At	: PRECISE AUTO SERVICE (HQ) NO 1 KAKI BUKIT AVE 6, #02-34/36 SINGAPORE 417883			Est. Duration of Repair	: 9.00

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,768.08
Revised Amount	:S\$	9,138.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,138.10
 Lump Sum Repair	:S\$	 7,300.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- (    ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.