

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 09.04.2020
Vehicle No: PA9870B
Owner: SIN U LIAN TRAVEL & COACH PTE LTD
Date of Accident: 07.04.2020
Make & Model: MITSUBISHI ROSA
Chassis No : BE63DJF00277

ESTIMATE FOR ACCIDENT VEHICLE NOS PA9870B

photo - * End panel X R

PARTS

- | | | | | |
|---|---|--------------------------|-----|-----|
| 1 | 1 | Rear bumper | / | CR4 |
| 2 | 1 | Rear bumper reflector RH | X | |
| 3 | 2 | Rear door RH/LH(repair) | X R | |
| 4 | 1 | Exhaust | / | hd |

SUB TOTAL
LESS 10 %
DISCOUNTED SUB TOTAL

#780

\$998.00
\$78.00
\$0.00
\$1,125.00
\$2,201.00
\$220.10
\$1,980.90

S. NETT ITEM

- | | | |
|---|---|------------------------|
| 1 | 1 | Rear door company logo |
|---|---|------------------------|

/ Nec

SUB TOTAL
LESS 0 %
DISCOUNTED SUB TOTAL

\$300.00 ²⁰⁰

\$300.00
\$0.00
\$300.00

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spraypainting on affected area x 3 colours |
| 3 | Apply putty and anti-corrosion to affected parts |

SUB TOTAL (LABOUR)

\$600.00 ⁷⁰⁰
\$1,000.00 ⁷⁰⁰
\$200.00 ⁵⁰
\$1,800.00

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

L/S
After paint photo.

Repair day - 3 days.

Sun P.m (Lkk)
05/06/2020.
TP without prejudice.