



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/LAW20005186/R1vf3s2

C/O TAN KOK QUAN PARTNERSHIP  
1 WALLICH STREET #07-02  
GUOCO TOWER SINGAPORE 078881

Date : 13-05-2020



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	SKL 511Z	<b>Veh. Inspected</b>	SJQ 7989T
<b>Policy No.</b>	2100483143	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	TWK/DAS/2124.18/AIG/PD	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MICHELLIE LIEW	<b>Assign Date</b>	14/04/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA COROLLA ALTIS 1.6 (A)	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	MR053ZEE106144330	<b>Colour</b>	GREY
<b>Odometer</b>	134764	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R15	YOKOHAMA	5 mm
<b>L/H Front Tyre</b>	205/60 R15	YOKOHAMA	5 mm
<b>R/H Rear Tyre</b>	205/60 R15	YOKOHAMA	5 mm
<b>L/H Rear Tyre</b>	205/60 R15	YOKOHAMA	5 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.  
REPAIR CONDITION SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	09/06/2018	<b>Inspection Date</b>	06/05/2020
<b>Survey held at</b>	ONE ZONE AUTOMOTIVE LLP NO 7 SOON LEE STREET ISPACE BUILDING #01-05 SINGAPORE 627608		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**