

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front bumper assy	grazed/cut	\$ 585.00	\$ 585.00
2	1	Front left bumper bracket	bent/necessary	\$ 45.00	\$ 45.00
3	1	Front left bumper retainer	bent/necessary	\$ 44.00	\$ 44.00
4	1	Front bumper reinforcement XAA SVC	bent/necessary	\$ 246.00	\$ 246.00
5	1	Front grille assy XAA SVC	warped/bent	\$ 170.00	\$ 170.00
6	1	Front grille emblem XAA SVC	necessary	\$ 68.00	\$ 68.00
7	1	Front left headlamp	grazed/cut	\$ 389.00	\$ 389.00
8	1	Front left fender assy repair	bent/warped	\$ 972.00	\$ 972.00
9	1	Front left fender vvti emblem	necessary	\$ 63.00	\$ 63.00
10	1	Front left fog lamp XAA SVC	bent	\$ 252.00	\$ 252.00
11	1	Front left fog lamp garnish XAA SVC	necessary	\$ 87.00	\$ 87.00
12	1	Front left suspension assy XAA SVC	bent	\$ 786.00	\$ 786.00
13	1	Front left lower arm XAA SVC	bent	\$ 371.00	\$ 371.00
14	1	Front left knuckle arm XAA SVC	bent	\$ 398.00	\$ 398.00
15	1	Front left wheel hub bearing XAA SVC	bent	\$ 251.00	\$ 251.00
				\$ 4,727.00	\$ 4,727.00
		Less 25%		\$ 1,181.75	\$ 1,181.75
				\$ 3,545.25	\$ 3,545.25
		<u>Special Nett Items</u>			
1	10	Front bumper clips	necessary	\$ 50.00	\$ 30 50.00
2	1	Front left sports rim XAA SVC	grazed/cut	\$ 650.00	\$ 650.00
				\$ 700.00	\$ 700.00
				\$ 4,245.25	\$ 4,245.25

1126
258
844.50

30

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 900.00	\$ 800.00 300
2	To putty and spray painting front left portion.	\$ 900.00	\$ 800.00 400
3	To apply anti rust proofing to front left affected area.	\$ 100.00	\$ 80.00 Xnn
4	To check wiring and focus front headlamp.	\$ 50.00	\$ 30.00 ✓
5	To remove and install front left undercarriage parts.	\$ 280.00	\$ 250.00 Xnn
6	To balance front left wheel.	\$ 50.00	\$ 30.00 Xnn
7	To conduct wheel alignment.	\$ 80.00	\$ 60.00 Xnn
Total labour :		\$ 2,360.00	\$ 2,050.00

730

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 4,245.25	\$ 4,245.25
Total labour :	\$ 2,360.00	\$ 2,050.00
Total repair cost :	\$ 6,605.25	\$ 6,295.25

Adjusted Repair Cost (Lump Sum Repair)

\$ 5,000.00

844.50

30.00

730.00

1604.50

20%

1283.60

↳ 1,300

3 days