



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20200409/0480		LOCATION OF FIRE: Along Ayer Rajah Expressway (AYE) towards Tuas Before Pioneer Road North Exit (Exit 18) Near lamp post No. 249/249A, Singapore	
FIRE REPORTED ON : 09 April 2020			
TIME OF CALL : 13:11:50 hrs			
STATION COVERAGE : Jurong Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The front left wheel of a Toyota Dyna lorry (GBC7891J).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a 38mm hose line jet from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Frictional heat at the front left wheel)			
DAMAGE SUSTAINED: As a result of the fire, the front left wheel, tyre and other components at the area were damaged. The front section of the lorry including the cabin, windscreen, as well as part of the carriage deck and side panels were also damaged. The contents of the carriage deck comprising industrial and other miscellaneous items sustained heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
 MUHAMMAD FAIZAL BIN MAZLAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.