



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC20000530/T1sf3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date : 24-04-2020



ATTN: HELENA

Code : INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMP 8191R	Veh. Inspected	SKG 2923G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078836-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	03/04/2020

#### 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 525i XL	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WBANU52000CZ90423	Colour	WHITE
Odometer	146800	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	245/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	245/45 R17	CONTINENTAL	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	04/01/2020	Inspection Date	08/01/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------