



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT20001541	Page	1
	64 CECIL STREET	Date	: 14. Apr 2020		
	#04-00 & #05-00 JOB BUILDING	Customer No.	: WZ1007		
	SINGAPORE 049711	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SLR9267B	Engine No	: L15B4532759		
Chassis No	: JHMRU1810GX202757	Date Time	: 14. Apr 2020 11:06:32 AM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: NG CHAN KEET	Survey Date	: HP : +65 8100 6306		
Ins Policy No.	: 19-MU009166-R01	Authorisation Date	: Email : arychua@honda.com.sg		
Date of Accident	: 13/4/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 746)						
	OWNER: NG CHAN KEET						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 13/04/2020@13.20PM						
	ACC: T/J TOA PAYOH L4(L/P23A)&TOA PAYOH CTL(L/P1)						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHA4241U - HYUNDAI/I40/BLUE TAXI						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNTR.	1	482.40	25	361.80	25.33	387.13
33552-T7A-J01	LAMP UNTL.	1	482.40	25	361.80	25.33	387.13
34150-T7A-J01	LIGHT ASSY,R.LID	1	276.90	25	207.67	14.54	222.21
34155-T7A-J01	LIGHT ASSYL LID	1	276.90	25	207.67	14.54	222.21
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
74090-T7A-J12ZC	GARNISH ASSYRR.LICENSE	1	198.60	25	148.95	10.43	159.38
38387-TZ5-A01	ANTENNA ASSYL.F.	1	60.80	25	45.60	3.19	48.79
74940-TZ5-A01	BUZZER ASSYSMART	1	62.00	25	46.50	3.26	49.76
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT	1	5.00	25	3.75	0.26	4.01
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
74410-T7B-003	PROTECTOR,R.RR.WHEEL ARCH	1	180.10	25	135.07	9.45	144.52

Printed on 14/4/2020 11:50:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT20001541	Page	2
	64 CECIL STREET	Date	: 14. Apr 2020		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZ1007		
	SINGAPORE 049711	Svc Advisor	: ARY CHUA WAI NGE		
Registration No	: SLR9267B	Engine No	: L15B4532759		
Chassis No	: JHMRU1810GX202757	Date Time	: 14. Apr 2020 11:06:32 AM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: NG CHAN KEET	Survey Date	:		
Ins Policy No.	: 19-MU009166-R01	Authorisation Date	:		
Date of Accident	: 13/4/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	96.50	25	72.37	5.07	77.44
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
71598-T7A-J00	SPACER,L.RR.BPR S	1	17.30	25	12.97	0.91	13.88
71501-T7B-000	FACE RR.BUMPER	1	798.10	25	347.78	41.90	640.47
66100-T7A-300ZZ	PANEL COMPR.	1	382.70	25	287.02	20.09	307.11
74440-T7A-003	WEATHERSTRIPTAILGATE	1	101.30	25	75.97	5.32	81.29
74800-T7A-J02	LOCK ASSYTAILGATE	1	86.20	25	64.65	4.53	69.18
68100-T7A-J20ZZ	TAIL GATE COMP	1	877.90	25	658.42	46.09	704.51
Sum Item					3760.71	263.28	4,023.99

BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	✓	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00	120	150.00	10.50	160.50
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00	140	180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	200	250.00	17.50	267.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	380.00	350	380.00	26.60	406.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	380.00	350	380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	400.00	300	400.00	28.00	428.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN WITH SEALANT	1	500.00	450	500.00	35.00	535.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	600.00	550	600.00	42.00	642.00
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	4800.00	2600	4800.00	336.00	5136.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3300.00	2600	3300.00	231.00	3531.00
Sum Labor					11190.00	783.30	11,973.30

Survey By: *mercus lkh*
Date & Time: *16/4/20 9.30am*

Printed on 14/4/2020 11:42:01 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To disassemble & resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15,997.29



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0096456 / NG CHAN KEET

Chassis No: JHMRU1810GX202757

License No: SLR9267B

Mileage: 72114

Engine No: L15B4532759

Document No: SVO20022391

Printed By: ARYCHUA

Order Date: 16. April 2020

Order Time: 11:06:32 AM

Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
SUPPLEMENTARY ITEM PARTS & LABOR							
84640-T7A-J01ZA	LINING ASSYRR.PANEL TWI	1	45.00	25	33.75	2.36	36.11
75722-T7W-A01	EMBLEMRR. nu	1	14.60	25	10.95	0.77	11.72
75725-T8N-T00	EMBLEM,RR. I-VTEC nu	1	15.90	25	11.92	0.83	12.75
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER nu	1	19.30	25	14.47	1.01	15.48
SUM PARTS:					71.09	4.97	76.06
TOTAL SGD					71.09	4.97	76.06

Total Payable (SGD)

76.06

GST Amount is calculated from individual line(s)