

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35284

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0368/2020/NS
Date : 8-Apr-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

10 days exclude 1 Sunday - jb

7-Aug-20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Ng Rui Zhi
Address : Blk 219 Bishan St 23
#12-289
Singapore 570219
Telephone : HP +65 97531539
Type of Claim : Own Damage Claims
Policy No. : 1900114746
Vehicle No : **SMM 4965 S**
Model Code : Audi A4 Sedan 2.0 TFSI S TRONIC
Model / Year : Jun-19
Engine No : CVK 079993
Chassis No : WAUZZZF41KN011524
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Apr-20
Place of Accident : Along CTE Tunnel Near Chin Swee Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMM 4965 S

S/N	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To remove and renew aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
3	To dismantle and renew front bumper, bonnet, both front fenders and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	6,300.00	\$ 3,250.00
4	To respray front bumper, bonnet, hinges and both front fenders.	\$	4,000.00	\$ 2,200.00
5	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 12,364.00	\$ 7,514.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

S/N	Parts Description	Damage Parts & Prices		
			S/Nett	Remarks
1	FRONT BUMPER	\$	2,068.00	\$ 1,654.40
2	FRONT BUMPER FIXING PARTS	\$	553.00	
3	FRONT BUMPER SECURING STRIP	2 \$	67.00	
4	FRONT BUMPER GRILLE - CENTRE	\$	185.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	198.00	
6	FRONT BUMPER AIR GUIDE - LH / RH	2 \$	118.00	
7	RADIATOR GRILLE	\$	1,254.00	\$ 1,003.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$	254.00	
9	FRONT BUMPER CARRIER	\$	757.00	\$ 605.20
10	FRONT BUMPER FOAM FILLER PIECE	\$	117.00	\$ 93.60
11	FRONT BUMPER COVER	\$	120.00	\$ 96.00
12	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$	68.00	
13	CAUTION SIGN STICKER	NEC \$	13.00	\$ 10.24
14	AIRCON STICKER	NEC \$	7.00	\$ 5.36
15	LOCK CARRIER BRACKET	\$	129.00	\$ 103.20
16	FRONT BUMPER SUPPORT - LH / RH	2 \$	54.00	\$ 42.24
17	FRONT PARKING AID SENSOR - INNER / OUTER	2	TBC	
18	FRONT PARKING AID SEAL RING	4 \$	14.00	
19	HORN - LH HIGH TONE	\$	38.00	
20	HORN - RH LOW TONE	\$	270.00	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,284.00	\$ 3,613.44

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

		Damage Parts & Prices			
S/N	Parts Description		S/Nett	Remarks	
		<i>c/f</i>		\$	3,613.44
21	SPRING SHACKLE - LH / RH	2	\$ 54.00		
22	FRONT FENDER - LH / RH	2	\$ 1,444.00	\$	577.60
23	FRONT FENDER ATTACHMENT PARTS		\$ 190.00		
24	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 94.00		
25	FRONT FENDER BRACKET - LH / RH	2	\$ 66.00	\$	26.24
26	STONE CHIP GUARD - LH / RH	2	\$ 96.00		
27	BONNET		\$ 2,634.00	\$	2,107.20
28	BONNET ATTACHMENT PARTS		\$ 388.00		
29	BONNET LID HINGE - LH / RH	2	\$ 574.00		
30	BONNET IMPACT PROTECTION - CENTRE		\$ 26.00	\$	20.56
31	BONNET IMPACT PROTECTION - LH / RH	2	\$ 52.00	\$	41.36
32	TOP FENDER LEDGE COVER - LH / RH INNER	2	\$ 58.00	\$	46.40
33	TOP FENDER LEDGE COVER - LH / RH OUTER	2	\$ 42.00	\$	33.44
34	BONNET GAS FILLED STRUT	2	\$ 224.00		
35	BONNET STRIKER - LH / RH	2	\$ 94.00	\$	75.04
36	BONNET LID LOCK	2	\$ 403.00	\$	322.40
37	BONNET BOWDEN CABLE - CENTRE		\$ 54.00	\$	43.20
38	BONNET BOWDEN CABLE		\$ 54.00	\$	43.20
39	BONNET RELEASE LEVER		\$ 13.00	\$	10.00
40	BONNET SOUND ABSORBER		\$ 323.00		
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,883.00	\$	6,960.08

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

S/N	Parts Description		Damage Parts & Prices		
			S/Nett	Remarks	
		<i>c/f</i>		\$	6,960.08
41	LED HEADLIGHT - LH / RH	2	\$ 14,642.00	\$	11,713.60
42	MAIN LIGHT ELECTRONICS POWER MODULE		\$ 732.00		
43	LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 707.00	\$	565.60
44	HEADLIGHT HOSE - LH		\$ 34.00		
45	HEADLAMP HOUSING REPAIR KIT - LH		\$ 124.00		
46	LIFT CYLINDER - LH / RH	2	\$ 396.00		
47	LIFT CYLINDER CORRUGATED PIPE		\$ 88.00		
48	LOCK CARRIER		\$ 956.00	\$	764.40
49	COOLANT REGULATOR SUPPORT	2	\$ 71.00		
50	EXTERNAL TEMPERATURE SENSOR		\$ 55.00		
51	TEMPERATURE SENSOR BRACKET		\$ 18.00	\$	13.68
52	AIRCON CONDENSER		\$ 586.00	\$	468.80
53	RADIATOR		\$ 766.00	\$	612.40
54	READY MIX COOLANT		\$ 176.00	\$	134.72
55	CHARGE AIR COOLER		\$ 552.00		
56	AIR INTAKE AIR DUCT - RH		\$ 21.00		
57	AIR INTAKE AIR GUIDE		\$ 50.00		
58	AIR INTAKE AIR FILTER		\$ 362.00		
59	AIR INTAKE AIR ASS METER		\$ 546.00		
60	AIR INTAKE HOSE		\$ 90.00		
61	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
62	SUPPLEMENTARY		\$ 2,201.00	\$	1,753.04
63	SUNDRIES		\$ 400.00	\$	46.64
TOTAL SPARE PARTS CHARGES			\$ 36,800.00	\$	23,092.96
TOTAL LABOUR CHARGES			\$ 12,364.00	\$	7,514.00
GRAND TOTAL			\$ 49,164.00	\$	30,606.96

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0368/2020/NS 26-May-20 Glory Tan 1 of 1 SMM 4965 S Audi A4 Sedan 2.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Radiator upper securing pin	\$ 6.00	
2	Radiator air guide inner LHS	\$ 27.00	\$ 21.04
3	Radiator air guide inner RHS	\$ 27.00	\$ 21.04
4	Radiator air guide outer LHS	\$ 12.00	\$ 8.88
5	Radiator air guide outer RHS	\$ 12.00	\$ 8.88
6	Radiator fan ring	\$ 240.00	\$ 191.60
7	Radiator fan with control unit	\$ 1,877.00	\$ 1,501.60
TOTAL		\$ 2,201.00	\$ 1,753.04

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant