

Premium Automobiles

10000 Road 1, Singapore 408659
Tel: 686 1321 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMM 4965 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	480
2	To remove and renew aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	1200
3	To dismantle and renew front bumper, bonnet, both front fenders and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00	3250 H.S. 27/05/20. 1250 (without lock carrier) 2500 (with lock carrier) 3250
4	To respray front bumper, bonnet, hinges and both front fenders.	\$ 4,000.00	1100 2200 H.S. 2200
5	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$ 384.00 ✓	384.
TOTAL LABOUR CHARGES		: \$ 12,364.00	

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	SPRING SHACKLE - LH / RH <i>new</i>	2 \$	54.00 *
22	FRONT FENDER - LH / RH <i>new RH Buckled</i>	2 \$	NN 1,444.00
23	FRONT FENDER ATTACHMENT PARTS	\$	190.00 *
24	FRONT FENDER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$	94.00 *
25	FRONT FENDER BRACKET LH / RH <i>Buckled</i>	2 \$	66.00 33. 26.20.
26	STONE CHIP GUARD - LH / RH	2 \$	96.00 *
27	BONNET <i>Dented</i>	\$	2,634.00 <i>207.20.</i>
28	BONNET ATTACHMENT PARTS <i>NN</i>	\$	388.00 *
29	BONNET LID HINGE - LH / RH <i>NN</i>	2 \$	574.00 *
30	BONNET IMPACT PROTECTION - CENTRE <i>new</i>	\$	26.00 <i>20.56</i>
31	BONNET IMPACT PROTECTION - LH / RH <i>new</i>	2 \$	52.00 <i>41.36</i>
32	TOP FENDER LEDGE COVER - LH / RH INNER <i>new</i>	2 \$	58.00 29. 46.40
33	TOP FENDER LEDGE COVER - LH / RH OUTER <i>new</i>	2 \$	42.00 21. 33.44.
34	BONNET GAS FILLED STRUT <i>new</i>	2 \$	224.00 +
35	BONNET STRIKER LH / RH <i>new Best</i>	2 \$	94.00 <i>75.04</i>
36	BONNET LID LOCK <i>new Dented</i>	2 \$	403.00 <i>322.40</i>
37	BONNET BOWDEN CABLE - CENTRE <i>new Dented</i>	\$	54.00 <i>43.20.</i>
38	BONNET BOWDEN CABLE <i>new Dented</i>	\$	54.00 <i>43.20.</i>
39	BONNET RELEASE LEVER <i>new Dented</i>	\$	13.00 <i>10.00.</i>
40	BONNET SOUND ABSORBER <i>new</i>	\$	323.00 *

SUB TOTAL SPARE PARTS CHARGES : \$ 6,883.00

Car-in

27/5/2020

Kiam/Hong

wip: 35284

Kiam/Hong**Premium Automobiles**55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>2 pced</i>	\$ 2,068.00 ✓	1654.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 553.00 ✓	
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 67.00 ✓	
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 185.00 ✓	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00 ✓	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2 \$ 118.00 ✓	
7	RADIATOR GRILLE <i>could</i>	\$ 1,254.00 ✓	1003.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$ 254.00 ✓	
9	FRONT BUMPER CARRIER <i>Best.</i>	\$ 757.00 ✓	605.20
10	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	\$ 117.00 ✓	93.60
11	FRONT BUMPER COVER <i>2 pced</i>	\$ 120.00 ✓	96.00
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$ 68.00 ✓	
13	CAUTION SIGN STICKER <i>3 new</i>	NEC \$ 13.00 ✓	10.26
14	AIRCON STICKER	NEC \$ 7.00 ✓	5.36
15	LOCK CARRIER BRACKET <i>could</i>	\$ 129.00 ✓	103.20
16	FRONT BUMPER SUPPORT - LH / RH <i>could</i>	2 \$ 54.00 ✓	42.24
17	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2 TBC ✓	
18	FRONT PARKING AID SEAL RING <i>new</i>	4 \$ 14.00 ✓	
19	HORN - LH HIGH TONE ?	\$ 38.00 ✗	
20	HORN - RH LOW TONE ?	\$ 270.00 ✗	
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,284.00	

AIQ- Achiam

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

S/N	Parts Description	Qty	Unit	Damage Parts & Prices		Remarks
				S/Nett		
41	LED HEADLIGHT - LH / RH <i>LH cond, RH?</i>	2	S	14,642.00	7321	14642. 11,713.60
42	MAIN LIGHT ELECTRONICS POWER MODULE <i>new</i>		S	732.00	X	
43	LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>		S	707.00	X	565.60
44	HEADLIGHT HOSE - LH <i>new</i>		S	34.00	+	
45	HEADLAMP HOUSING REPAIR KIT - LH <i>new</i>		S	124.00	+	
46	LIFT CYLINDER - LH / RH <i>new</i>	2	S	396.00	+	
47	LIFT CYLINDER CORRUGATED PIPE <i>new</i>		S	88.00	+	
48	LOCK CARRIER <i>cond</i>		S	956.00	✓	766.80
49	COOLANT REGULATOR SUPPORT <i>new</i>	2	S	71.00	X	
50	EXTERNAL TEMPERATURE SENSOR <i>new</i>		S	55.00	X	
51	TEMPERATURE SENSOR BRACKET <i>cond</i>		S	18.00	✓	13.68
52	AIRCON CONDENSER <i>Best</i>		S	586.00	✓	468.80
53	RADIATOR <i>Best</i>		S	766.00	✓	612.40
54	READY MIX COOLANT <i>new</i>		S	176.00	✓	130.72
55	CHARGE AIR COOLER <i>new</i>		S	552.00	X	
56	AIR INTAKE AIR DUCT - RH <i>new</i>		S	21.00	+	
57	AIR INTAKE AIR GUIDE <i>new</i>		S	50.00	+	
58	AIR INTAKE AIR FILTER <i>new</i>		S	362.00	+	
59	AIR INTAKE AIR ASS METER <i>new</i>		S	546.00	+	
60	AIR INTAKE HOSE <i>new</i>		S	90.00	+	
61	FRONT NO PLATE <i>Best</i>		S/N	60.00	-	60
62	SUNDRIES <i>new</i>		S	400.00	✓	46.64
TOTAL SPARE PARTS CHARGES				:	\$	34,599.00
TOTAL LABOUR CHARGES				:	\$	12,364.00
GRAND TOTAL				:	\$	46,963.00

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Add part see behind