

Premium Automobiles

100, 100 Road 1, Singapore 408699
Tel: 65 4321 1183 Fax: 65 4321 1183

Telex

Estimated Labour Charges for Accident Vehicle SMM 4965 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N S 480.00 ✓	480
2	To remove and renew aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N S 1,200.00 ✓	1200
3	To dismantle and renew front bumper, bonnet, <u>both front fenders and both headlights</u> . To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts reoved.	S 6,300.00 ✓	3250 H.S. 27/05/20. 1250 (without lock carrier) 2500 (with lock carrier) 3000
4	To respray front bumper, bonnet, hinges and <u>both front fenders</u> .	S 4,000.00 ✓	1100 2200 H.S. 2200
5	To carry out pre-diagnostic check and post-diagnostic check.	S/N S 384.00 ✓	384
TOTAL LABOUR CHARGES		: S 12,364.00	

Car-in

27/5/2020

Kiam/Hong

wip: 35284

Kiam/Hong

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>2nd</i>	\$ 2,068.00	✓ 1654.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 553.00	✓
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$ 67.00	✓
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 185.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00	✓
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2 \$ 118.00	✓
7	RADIATOR GRILLE <i>crushed</i>	\$ 1,254.00	✓ 1003.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$ 254.00	✓
9	FRONT BUMPER CARRIER <i>Best.</i>	\$ 757.00	✓ 605.20
10	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	\$ 117.00	✓ 93.60
11	FRONT BUMPER COVER <i>crushed</i>	\$ 120.00	✓ 96.00
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$ 68.00	✓
13	CAUTION SIGN STICKER <i>3</i>	NEC \$ 13.00	✓ 10.20
14	AIRCON STICKER	NEC \$ 7.00	✓ 5.36
15	LOCK CARRIER BRACKET <i>crushed</i>	\$ 129.00	✓ 103.20
16	FRONT BUMPER SUPPORT - LH / RH <i>crushed</i>	2 \$ 54.00	✓ 42.20
17	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2 TBC	✓
18	FRONT PARKING AID SEAL RING <i>new</i>	4 \$ 14.00	✓
19	HORN - LH HIGH TONE ?	\$ 38.00	✗
20	HORN - RH LOW TONE ?	\$ 270.00	✗
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,284.00	

AIG - Action

Premium Automobiles
55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

			Damage Parts & Prices	
S/N	Parts Description		S/Nett	Remarks
21	SPRING SHACKLE - LH / RH <i>new</i>	2 \$	54.00	*
22	FRONT FENDER - LH / RH <i>new RH Buckled</i>	2 \$	1,444.00	577.60
23	FRONT FENDER ATTACHMENT PARTS	\$	190.00	*
24	FRONT FENDER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$	94.00	*
25	FRONT FENDER BRACKET LH / RH <i>Buckled new</i>	2 \$	66.00	33. 26.20.
26	STONE CHIP GUARD - LH / RH	2 \$	96.00	*
27	BONNET <i>Dented</i>	\$	2,634.00	2107.20.
28	BONNET ATTACHMENT PARTS <i>2 NN</i>	\$	388.00	*
29	BONNET LID HINGE - LH / RH <i>2 NN</i>	2 \$	574.00	*
30	BONNET IMPACT PROTECTION - CENTRE <i>2 new</i>	\$	26.00	20.56
31	BONNET IMPACT PROTECTION - LH / RH <i>new</i>	2 \$	52.00	41.36
32	TOP FENDER LEDGE COVER - LH / RH INNER <i>new RH</i>	2 \$	58.00	29. 46.40
33	TOP FENDER LEDGE COVER - LH / RH OUTER <i>new</i>	2 \$	42.00	21. 33.40.
34	BONNET GAS FILLED STRUT <i>new</i>	2 \$	224.00	+
35	BONNET STRIKER LH / RH <i>new Best</i>	2 \$	94.00	75.04
36	BONNET LID LOCK <i>new Dargd</i>	2 \$	403.00	322.40
37	BONNET BOWDEN CABLE - CENTRE <i>new Dargd</i>	\$	54.00	43.20.
38	BONNET BOWDEN CABLE <i>new Dargd</i>	\$	54.00	43.20.
39	BONNET RELEASE LEVER <i>new Dargd</i>	\$	13.00	10.00.
40	BONNET SOUND ABSORBER <i>new</i>	\$	323.00	*

SUB TOTAL SPARE PARTS CHARGES : \$ 6,883.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMM 4965 S

S/N	Parts Description	Qty	Unit	Damage Parts & Prices		Remarks
				S/Nett		
41	LED HEADLIGHT - LH / RH <i>LH could, RH?</i>	2	S	14,642.00	7321	14642. 11,713.60
42	MAIN LIGHT ELECTRONICS POWER MODULE <i>new</i>		S	732.00	X	
43	LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>		S	707.00	X	565.60
44	HEADLIGHT HOSE - LH <i>new</i>		S	34.00	+	
45	HEADLAMP HOUSING REPAIR KIT - LH <i>new</i>		S	124.00	+	
46	LIFT CYLINDER - LH / RH <i>new</i>	2	S	396.00	+	
47	LIFT CYLINDER CORRUGATED PIPE <i>new</i>		S	88.00	+	
48	LOCK CARRIER <i>could</i>		S	956.00	✓	764.80
49	COOLANT REGULATOR SUPPORT <i>new</i>	2	S	71.00	X	
50	EXTERNAL TEMPERATURE SENSOR <i>new</i>		S	55.00	X	
51	TEMPERATURE SENSOR BRACKET <i>could</i>		S	18.00	✓	13.68
52	AIRCON CONDENSER <i>Best</i>		S	586.00	✓	468.80
53	RADIATOR <i>Best</i>		S	766.00	✓	612.40
54	READY MIX COOLANT <i>new</i>		S	176.00	✓	130.72
55	CHARGE AIR COOLER <i>new</i>		S	552.00	X	
56	AIR INTAKE AIR DUCT - RH <i>new</i>		S	21.00	+	
57	AIR INTAKE AIR GUIDE <i>new</i>		S	50.00	+	
58	AIR INTAKE AIR FILTER <i>new</i>		S	362.00	X	
59	AIR INTAKE AIR ASS METER <i>new</i>		S	546.00	+	
60	AIR INTAKE HOSE <i>new</i>		S	90.00	+	
61	FRONT NO PLATE <i>Best</i>		S/N	60.00	✓	60
62	SUNDRIES <i>new</i>		S	400.00	✓	46.64

TOTAL SPARE PARTS CHARGES	:	\$ 34,599.00
TOTAL LABOUR CHARGES	:	\$ 12,364.00
GRAND TOTAL	:	\$ 46,963.00

All charges are not inclusive of GST.
Legend Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Add part see behind

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0368/2020/NS

Date

26-May-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMM 4965 S

Model No

Audi A4 Sedan 2.0 TFSI S TRON.

Quantity	Description	Unit Price	Amount
Parts			
1	Radiator upper securing pin <i>encl NN</i>	\$ 6.00	✓
2	Radiator air guide inner LHS	\$ 27.00	✓ 21.04
3	Radiator air guide inner RHS	\$ 27.00	✓ 21.04
4	Radiator air guide outer LHS <i>encl</i>	\$ 12.00	✓ 8.88
5	Radiator air guide outer RHS	\$ 12.00	✓ 8.88
6	Radiator fan ring <i>encl</i>	\$ 240.00	✓ 191.60
7	Radiator fan with control unit <i>encl</i>	\$ 1,877.00	✓ 1501.60
TOTAL		\$ 2,201.00	

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
27/05/20

Authorised Signature

Repair Days: 10 Days