

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA	DATE	: 14-Apr-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SKX5332C		
MODEL	: HONDA VEZEL 1.5X CVT	Jasper	
CHASSIS NO	:		
ACCIDENT DETAILS		DATE	: 13-Apr-20
		TIME	: 12:35HR
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,250.30	\$ 1,250.30
2	TAILGATE EMBLEM "VEZEL" <i>new</i>	1	\$ 76.80	\$ 76.80
3	TAILGATE INNER LOCK <i>Dented</i>	1	\$ 256.00	\$ 256.00
4	TAILGATE INNER TRIM <i>new</i>	1	\$ 310.00	\$ 310.00
5	TAILGATE WEATHER STRIP <i>ut</i>	1	\$ 211.00	\$ 211.00
6	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 145.00	\$ 145.00
7	REAR BUMPER <i>Dented</i>	1	\$ 965.00	\$ 965.00
8	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 56.00	\$ 112.00
9	REAR END PANEL <i>Dented</i>	1	\$ 588.30	\$ 588.30
10	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 136.50	\$ 136.50

Rear Center Bumper
Cost

3143.60

2514.88

TOTAL PRICE \$4,050.90

LESS 20% \$ 810.18

SUB TOTAL PRICE \$3,240.72

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAILGATE INNER TRIM CLIP <i>new</i>	1	\$ 20.00	\$ 20.00
2	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR BUMPER CLIPS <i>new</i>	1	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
5	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1	\$ 20.00	\$ 20.00

6	REVERSE SENSOR <i>changed</i>	1	\$ 220.00	\$ 220.00 <i>200</i>
350			TOTAL	\$400.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING(REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00	1000 800	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	1000 700	
3	WIRING CHECK	\$ 60.00	60 30	
4	TUFF COAT	\$ 150.00	150 60	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	100 50	
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	100 30	
7	TRANSFER TAILGATE MECHANISM	\$ 120.00	120 60	
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 140.00	140 120	
TOTAL		\$ 2,670.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$3,640.72
TOTAL LABOUR COST : \$2,670.00
TOTAL REPAIR COST : \$6,310.72

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adnan
L/S 15/04/20
06 days

total: 4734.88

L/S: 37K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: