



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 13/4/2020

Vehicle: GBA1881M

Make / Model: FIAT DOBLO

Chassis: ZFA22300005500012

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	LH FRONT DOOR / <i>DD</i>	1	\$ 2,450.80	\$ 2,450.80
2	LH FRONT DOOR HING TOP <i>X</i>	1	\$ 189.00	\$ 189.00
3	LH FRONT DOOR HING BOTTOM <i>X</i>	1	\$ 189.00	\$ 189.00
4	LH FRONT DOOR CHECKER <i>X</i>	1	\$ 155.00	\$ 155.00
5	LH FRONT DOOR LOCK ?	1	\$ 596.00	\$ 596.00
6	LH FRONT DOOR LOCK CATCH <i>X</i>	1	\$ 112.00	\$ 112.00
7	LH FRONT DOOR PROTECTOR / <i>CUT</i>	1	\$ 167.00	\$ 167.00
8	LH FRONT DOOR CENTER PILLAR OUTRE PANEL <i>X R</i>	1	\$ 1,675.00	\$ 1,675.00
9	LH REAR DOOR / <i>DD</i>	1	\$ 1,769.50	\$ 1,769.50
10	LH REAR DOOR HING TOP <i>X</i>	1	\$ 189.00	\$ 189.00
11	LH REAR DOOR HING BOTTOM ?	1	\$ 189.00	\$ 189.00
12	LH REAR DOOR CHEKCEK <i>X</i>	1	\$ 155.00	\$ 155.00
13	LH REAR DOOR LOCK <i>X</i>	1	\$ 623.00	\$ 623.00
14	LH REAR DOOR LOCK CATCH <i>X</i>	1	\$ 134.00	\$ 134.00
15	LH REAR DOOR PROTECTOR / <i>CUT</i>	1	\$ 187.00	\$ 187.00
16	REAR BUMPER LH / <i>DR / CUT</i>	1	\$ 457.80	\$ 457.80
17	REAR BUMPER SIDE RETAINER LH / <i>DR</i>	1	\$ 89.00	\$ 89.00
18	LH REAR TAILLAMP <i>X</i>	1	\$ 897.00	\$ 897.00
19	LH REAR WHEEL CAP <i>CUT</i>	1	\$ 250.00	\$ 250.00
				\$ 10,474.10
			Less 10%	\$ 1,047.41
			Total	\$ 9,426.69
	S/Nett items:			
1	LH FRONT DOOR COMPANY STICKER / <i>1pc</i>	1	\$ 18.00	\$ 18.00
2	REAR BUMPER CLIP / <i>1pc</i>	1 SET	\$ 80.00	\$ 80.00
3	MISCELLANEOUS <i>X</i>		\$ 300.00	\$ 300.00
				\$ 398.00

30

GBA1881M

Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND REFIX REAR UPHOLSTERY/CARPET	1	\$ 200.00	\$ 200.00
3	CHECK AND TEST FOR WATER LEAKAGE	1	\$ 150.00	\$ 150.00
4	REMOVE AND TRANSFER LH FRONT DOOR FITTING	1	\$ 200.00	\$ 200.00
5	REMOVE AND TRANSFER LH REAR DOOR FITTING	1	\$ 200.00	\$ 200.00
6	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
8	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
9	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00
				\$ 3,580.00
			Parts Replacement Amount	\$ 9,824.69
			Total Amount for Labour	\$ 3,580.00
			Total Amount	\$ 13,404.69

30
X
X
80
80
30
X : 800
600

Steve (LKK) with AL
14/4/20, 3.45pm

L/S

Ry AL sy
5 dys

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: