

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35035

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0362/2020/NS
Date	:	6-Apr-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Dr Cheong Hui Ting Elizabeth (zhang Huiting)
Address	:	260A Lorong Chuan Singapore 556757
Telephone	:	HP +65 96881203
Type of Claim	:	Own Damage Claims
Policy No.	:	1800086489-01
Vehicle No	:	SME 130 C
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Jul-18
Engine No	:	CHZ 468675
Chassis No	:	WAUZZZ8V8J1070243
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Apr-20
Place of Accident	:	CTE Towards City Just Before Braddell Road Exit

Premium Automobiles

55, Hill Road 1, Singapore 408797
Tel: 6366 2123 Fax: 6841 1103

Telefax

Estimated Labour Charges for Accident Vehicle SME 130 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, bonnet, both front fenders and both headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 4,200.00	1000 + 250 Fender = 1250.
3	To respray front bumper, bonnet, hinges and both front fenders.	\$ 4,000.00	2200
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 130 C

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
1	FRONT BUMPER <i>Dislod</i>	\$	1,894.00	✓
2	FRONT BUMPER FIXING PARTS <i>not in</i>	\$	176.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	72.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>could</i>	\$	151.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	505.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$	560.00	+
7	FRONT BUMPER COVER TRIM - LH / RH ?	2 \$	306.00	?
8	WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	2 \$	72.00	+
9	RADIATOR GRILLE <i>could</i>	\$	1,338.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$	180.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>not</i>	2 \$	354.00	✓
12	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$	681.00	?
13	FRONT BUMPER FOAM FILLER PIECE ?	\$	178.00	?
14	FOAM FILLER PIECE COVER ?	\$	115.00	?
15	AIRCON STICKER <i>new</i>	NEC \$	7.00	✓
16	CAUTION SIGN STICKER <i>new</i>	NEC \$	13.00	✓
17	SIGNAL HORN RETAINER - LH HIGH TONE ?	\$	188.00	?
18	SIGNAL HORN RETAINER - RH LOW TONE ?	\$	188.00	?
19	BONNET <i>Buckled</i>	\$	2,988.00	✓
20	BONNET ATTACHMENT PARTS ?	\$	155.00	?
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 10,121.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408605
Tel: 6366 2323 Fax: 6341 1181

Telefax

Material List for Accident Vehicle Regn No. SME 130 C

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
21	BONNET LID HINGE - LH / RH ?	2	\$ 116.00	?
22	BONNET EDGE PROTECTION <i>MC</i>		\$ 26.00	✓
23	BONNET STRIKER - LH / RH <i>MC</i>	2	\$ 208.00	✓
24	BONNET GAS FILLED STRUT <i>MC</i>		\$ 112.00	✓
25	BONNET CATCH HOOK		\$ 84.00	+
26	BONNET CATCH HOOK <i>MC</i>		\$ 60.00	✓
27	BONNET LID LOCK	2	\$ 403.00	✓
28	BONNET BOWDEN CABLE - CENTRE <i>MC</i>		\$ 54.00	+
29	FRONT FENDER - LH / RH <i>Regis</i>	2	\$ 1,604.00	+
30	FRONT FENDER ATTACHMENT PARTS <i>MC</i>		\$ 68.00	+
31	LED HEADLIGHT - LH / RH ?	2	\$ 10,386.00	?
32	LIFT CYLINDER - LH / RH <i>MC</i>	2	\$ 268.00	+
33	LIFT CYLINDER HOSE <i>MC</i>		\$ 64.00	+
34	RADIATOR AIR GUIDE - LH / RH <i>MC</i>	2	\$ 46.00	+
35	RADIATOR AIR GUIDE - UPPER CENTRE <i>MC</i>		\$ 12.00	+
36	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
37	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 24,092.00	
TOTAL LABOUR CHARGES		:	\$ 8,752.00	
GRAND TOTAL		:	\$ 32,844.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Adnan

Surveyed Date

: 14/04/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 06 Days

Link Auto Consultants henceforth
the Repairer of the following:

- To survey before/after spray painting
- To replace damaged part(s) during warranty
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resubmitted and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant