

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khan@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35035

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/00/0362/2020/N5
Date : 6-Apr-20

2336128.

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Dr Cheong Hui Ting Elizabeth (zhang Huiting)
Address : 260A Lorong Chuan
Singapore 556757
Telephone : HP +65 96881203
Type of Claim : Own Damage Claims
Policy No. : 1800086489-01
Vehicle No : **SME 130 C**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jul-18
Engine No : CHZ 468675
Chassis No : WAUZZZ8V8J1070243
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Apr-20
Place of Accident : CTE Towards City Just Before Braddell Road Exit

Premium Automobiles

57, Old Road 1, Singapore 408629
Tel: 6365 2121 Fax: 6341 1181

Telefax

Estimated Labour Charges for Accident Vehicle SME 130 C

S/N Nature of Jobs

- 1 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.

Estimated Charges Surveyor's Recommendations

S/N \$ 360.00 ✓ ✓

- 2 To dismantle and renew front bumper, bonnet, both front fenders and both headlight. Re-organise crash management components. Reinstall all parts removed.

\$ 4,200.00

1000 + 250 = 1250

2250

- 3 To respray front bumper, bonnet, hinges and both front fenders.

\$ 4,000.00

2200

S/N \$ 192.00 ✓ ✓

- 4 To carry out diagnostic check.

: \$ 8,752.00

TOTAL LABOUR CHARGES

Premium Automobiles

55 Ubi Road 1, Singapore 408609
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 130 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>Dislod</i>	\$ ✓ 1,894.00 ✓	1515.2
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 176.00 +	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$ 72.00 +	
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ ✓ 151.00 ✓	120.4
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 505.00 +	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	\$ 560.00 +	
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	\$ 306.00 +	
8	WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	\$ 72.00 +	
9	RADIATOR GRILLE <i>new</i>	\$ ✓ 1,338.00 ✓	1070.4
10	RADIATOR GRILLE CLOSING ELEMENT <i>new</i>	\$ 180.00 +	143.6
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	\$ ✓ 354.00 ✓	282.4
12	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>new</i>	\$ ✓ 681.00 ✓	544.8
13	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ ✓ 178.00 ✓	142.4
14	FOAM FILLER PIECE COVER <i>new</i>	\$ ✓ 115.00 ✓	91.6
15	AIRCON STICKER <i>new</i>	NEC \$ ✓ 7.00 ✓	5.36
16	CAUTION SIGN STICKER <i>new</i>	NEC \$ ✓ 13.00 ✓	10.24
17	SIGNAL HORN RETAINER - LH HIGH TONE <i>new</i>	\$ 188.00 +	
18	SIGNAL HORN RETAINER - RH LOW TONE <i>new</i>	\$ 188.00 +	
19	BONNET <i>new</i>	\$ ✓ 2,988.00 ✓	2390.40
20	BONNET ATTACHMENT PARTS <i>new</i>	\$ 155.00 +	
SUB TOTAL SPARE PARTS CHARGES		: <u>\$ 10,121.00</u>	

Premium Automobiles

50, Old Road, Singapore 308095
Tel: 6346 2424 Fax: (65) 1110

Telefax

Material List for Accident Vehicle Regn No. SME 130 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET LID HINGE - LH / RH <i>2H nec</i>	2 \$	116.00 <i>X</i>
22	BONNET EDGE PROTECTION <i>MC</i>	✓ \$	26.00 ✓ 20.8
23	BONNET STRIKER - LH / RH <i>MC</i>	2 \$	208.00 <i>✓</i>
24	BONNET GAS FILLED STRUT <i>MC</i>	\$	112.00 <i>X</i>
25	BONNET CATCH HOOK <i>2</i>	\$	84.00 <i>+</i>
26	BONNET CATCH HOOK <i>MC</i>	✓ \$	60.00 ✓ 47.44
27	BONNET LID LOCK	2 \$	403.00 <i>✓</i>
28	BONNET BOWDEN CABLE - CENTRE <i>MC</i>	\$	54.00 <i>+</i>
29	FRONT FENDER - LH / RH <i>Both RH Buckled</i>	2 ✓ \$	1,604.00 <i>X</i> 641.2
30	FRONT FENDER ATTACHMENT PARTS <i>MC</i>	\$	68.00 <i>+</i>
31	LED HEADLIGHT - LH / RH <i>2 Buckled</i>	2 ✓ \$	10,386.00 <i>?</i> 8308.8
32	LIFT CYLINDER - LH / RH <i>MC</i>	2 \$	268.00 <i>X</i>
33	LIFT CYLINDER HOSE <i>MC</i>	\$	64.00 <i>X</i>
34	RADIATOR AIR GUIDE - LH / RH <i>MC</i>	2 ✓ \$	46.00 <i>+</i> 36.32
35	RADIATOR AIR GUIDE - UPPER CENTRE <i>MC</i>	\$	12.00 <i>+</i>
36	FRONT NO PLATE <i>Det'd</i>	S/N ✓ \$	60.00 ✓ 60
37	SUNDRIES <i>Nec.</i>	✓ \$	400.00 <i>?</i> 61.52
TOTAL SPARE PARTS CHARGES		:	\$ 24,092.00
TOTAL LABOUR CHARGES		:	\$ 8,752.00
GRAND TOTAL		:	\$ 32,844.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Adnan

Surveyed Date

: 11/04/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 08 Days

08 Days
H. H.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Consultants hence
of the following
• After spray p
• Part(s) durin
• This is on a "With
• No (s) is allow
• Supp (s) must be
is subject to approval from Ins.

Acknowledged, a rer
Signature:
Date:

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0362/2020/NS 6-May-20 Glory Tan 1 of 1 SME 130 C Audi A3 Sedan 1.0 TFSI 8V
Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>cracked</i>	\$ 685.00	\$ 547.60 ✓
2	Liquid coolant for lock carrier <i>New</i>	\$ 86.00	\$ 68.80 ✓
			\$ 616.40
Labours			
1	To remove and reinstall aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	\$ 1,200.00 ✓
2	To remove and renew front lock carrier and align to position.	\$ 2,800.00	\$ 1,500.00 1250.
TOTAL		\$ 4,771.00	\$ 3,316.40

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0362/2020/NS 8-May-20 Glory Tan 1 of 1 SME 130 C Audi A3 Sedan 1.0 TFSI 8V
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Air intake duct air guide <i>Rehd</i>	\$ 54.00	SUNDRY ✓
TOTAL		\$ 54.00	SUNDRY

For Premium Automobiles Pte Ltd

Authorised Signature