

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CS/C7120005216/Uvf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV)

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Consistent?: Yes or No

Consistent?: Yes or No

Res.: Yes or No

3 Val.: Yes or No

Vehicle: IN / OUT

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.:(\$)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NR / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

Not Authorised
16/4/20
2/5 2100
2 days
Take photo after repair
M001028

M/S : CHINA TAIPING INSURANCE

Estimate No:

Date: 17-Mar-20

Veh Reg No: XD4698E

Make/Model: MITSUBISHI

Chassis No: FV51JJA00701

Engine No: 6M70445862

Reg. Date : 21/04/2011

ATTN: Motor Claim Department

Your Ref No: XD4698E

Claim Type: Third Party

Accident Date: 03/12/2019

Estimate Repair Cost to Vehicle No :XD4698E

PAGE: 1/1

S/N	Description	Quantity	Unit	Price	Amount
<u>NETT PRICE</u>				<u>SS</u>	<u>SS</u>
1	Front Bumper 2200.83	1	PCS	3950.00	3950.00
2	Front Bumper Corner Garnish - LH 154	1	PCS	296.00	296.00
3	Front HeadLamp - LH one	1	PCS	1100.00	1100.00
4	Front HeadLamp Rim - LH one	1	PCS	145.00	145.00
5	Front Bumper Lamp - LH 11	1	PCS	368.00	368.00
6	Front Bumper Lamp Cover - LH ground	1	PCS	117.00	117.00
7	Front Step Panel Garnish - LH 12	1	PCS	346.00	346.00
8	Front Step Panel Garnish Lower - LH 12	1	PCS	325.00	325.00
TOTAL				251%	6647.00

LABOUR CHARGES

12	Panel Beating	380	950.00
13	Spray Paint	300	750.00

TOTAL	1700.00
OVERALL TOTAL	8347.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR FOCUS AUTO PTE LTD

AUTHORISE SIGNATURE

2-2616.83
253
9-1962.62
1-680.00
2542.62
2114.