

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



1/52: Chassis Number




2/52: Odometer Reading



3/52: General View



4/52: General View



5/52: General View



6/52: General View


SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



7/52: General View



8/52: General View



9/52: General View



10/52: General View



11/52: General View



12/52: General View

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



13/52: General View




14/52: General View



15/52: General View



16/52: General View



17/52: General View



18/52: General View

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



19/52: General View



20/52: General View



21/52: General View



22/52: General View



23/52: General View



24/52: General View

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



25/52: General View



26/52: General View



27/52: General View



28/52: General View




29/52: General View



30/52: General View

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



31/52: General View



32/52: General View



33/52: General View



34/52: General View



35/52: General View



36/52: General View

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



37/52: General View




38/52: General View



39/52: General View



40/52: General View



41/52: General View



42/52: General View

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)




43/52: General View



44/52: After Repair Photo



45/52: After Repair Photo



46/52: After Repair Photo



47/52: After Repair Photo



48/52: After Repair Photo

SMC688X [SJU1999H] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



49/52: After Repair Photo



50/52: After Repair Photo



51/52: After Repair Photo



52/52: After Repair Photo