



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9330K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	TO REPAIR SEE LABOUR	985.60	-
1	BOOT LID ELANTRA	NECESSARY	45.00	45.00
1	BOOT LID EMBLEM S	NECESSARY	28.00	28.00
1	BOOT LID LOGO	NECESSARY	41.20	41.20
2	REAR BUMPER SIDE RETAINER @\$36.90	SERVICEABLE	73.80	-
1	REAR BUMPER REINFORCEMENT	BENT	402.56	402.56
2	REAR BUMPER BRACKET @\$90.00	SERVICEABLE	180.00	-
2	REAR BUMPER REFLECTOR @\$115.00	O/S SCRATCHED	230.00	115.00
1	REAR BUMPER	CRUMPLED	1,025.50	654.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	134.50	-
2	TAIL LAMP @\$412.00	SERVICEABLE	824.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	421.00	-
1	REAR BUMPER LOWER	CUT	452.00	452.00
	LESS 20% DISCOUNT		-968.63	-347.55
			3,874.53	1,390.21
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			300.00	230.00
<u>LABOUR</u>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR END PANEL.		540.00	300.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		550.00	400.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		25.00	25.00
	WIRING AND BULB CHECKING.		22.50	22.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING.		76.50	30.00
			1,214.00	777.50
GRAND TOTAL			5,388.53	2,397.71
RECOMMENDED COST OF REPAIRS				2,397.71

Report Ref No. CS3/SMO20004070/Qtf3e2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.