



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 35967

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 14/04/2020
CLAIM NO. : 11541
POLICY NO. : MC/00706405

FROM : HASRIANAH

VEHICLE NO. : FBK3722Z
MAKE/MODEL : /

Not Authorised
huc
2/5/20
4 days
16/4/20
take 2 hrs After repair

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BODY COWLING LH P/N: 54009	REPLACE	1.00	\$136.00	Cur 136.00
2	BOX REAR (COOCASE) 60L P/N: 56161	REPLACE	1.00	\$720.00	Cur 720.00
3	CASE CHAIN 2 P/N: 45916	REPLACE	1.00	\$17.00	Cur 17.00
4	COVER TAIL LH P/N: 53757	REPLACE	1.00	\$208.00	Cur 208.00
5	COVER, 1	REPLACE	1.00	\$14.00	14.00
6	DAMPER 1 P/N: 54010	REPLACE	1.00	\$2.00	2.00
7	DAMPER 4 (BOARD FOOTREST) P/N: 45963	REPLACE	1.00	\$3.00	3.00
8	DAMPER LOCATING 2 P/N: 45965	REPLACE	1.00	\$7.00	7.00
9	DAMPER PLATE P/N: 45966	REPLACE	1.00	\$7.00	7.00
10	EMBLEM P/N: 47701	REPLACE	1.00	\$28.00	28.00
11	EMBLEM (SIDE COVER) P/N: 40466	REPLACE	1.00	\$83.00	83.00
12	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	16.00	\$69.00	350 1,104.00
13	LEG SHIELD 1 P/N: 45967	REPLACE	1.00	\$251.00	Cur 251.00

*35967 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER 1 P/N: 54007	REPLACE	1.00	\$58.00	58.00 ✓
15	MIRROR REAR VIEW LH ASSY P/N: 54008	REPLACE	1.00	\$104.00	104.00 ✓
16	MOLE SIDE COVER 1 P/N: 45911	REPLACE	1.00	\$171.00	171.00 ✓
17	PLATE 1 P/N: 45988	REPLACE	1.00	\$27.00	27.00 ?
18	STAND MAIN P/N: 53751	REPLACE	1.00	\$191.00	191.00 X

SUB TOTAL

\$3,131.00

GST @ 7 %

\$219.17

GRAND TOTAL

\$3,350.17

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*35967 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015