

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-059
DATE : 15-Apr-2020
POLICY NO. : P10351573R00
VEHICLE REG. NO. : SJD57605
VEHICLE MAKE : MITSUBISHI LANCER 1.5 MIVEC GLS 4A/1

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Bumper / PD.	1	\$ 700.00	\$ 700.00
2	Rear Bumper Clip / NEC	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <i>we ? X SVC</i>	1	\$ 45.00	\$ 45.00
4	Rear Bumper Retainer LH / BR	1	\$ 45.00	\$ 45.00
5	Rear Bumper Reflector LH / BR	1	\$ 60.00	\$ 60.00
6	Rear Tail Lamp LH ? / CRA	1	\$ 420.00	\$ 420.00
7	Rear Tail Lamp Grommet Upper ? / NEC	1	\$ 10.00	\$ 10.00
8	Rear Tail Lamp Grommet Lower ? / NEC	1	\$ 10.00	\$ 10.00
9	Rear Bootlid X R	1	\$ 700.00	\$ 700.00
10	Rear Bootlid Lock X SVC	1	\$ 80.00	\$ 80.00
11	Rear Bootlid Hinge RH X SVC	1	\$ 50.00	\$ 50.00
12	Rear Bootlid Hinge LH X SVC	1	\$ 50.00	\$ 50.00
13	Rear Bootlid Seal ? X SVC	1	\$ 180.00	\$ 180.00
14	Rear Mitsubishi Emblem / NEC	1	\$ 60.00	\$ 60.00
15	Rear Lancer Emblem / NEC	1	\$ 60.00	\$ 60.00
16	Rear EX Emblem / NEC	1	\$ 60.00	\$ 60.00
17	Rear Mivec Emblem / NEC	1	\$ 60.00	\$ 60.00
18	Rear Reinforcement / BT	1	\$ 360.00	\$ 360.00
19	End Panel ? / PD	1	\$ 420.00	\$ 420.00
20	End Panel Garnish ? / CR4	1	\$ 180.00	\$ 180.00
21	Rear Spare Tire Sink/ Panel ? X R	1	\$ 650.00	\$ 650.00
Total Spare Parts				\$ 4,250.00
<u>SPECIAL NETT</u>				
22	Rear License Plate with Casing / CR4	1	\$ 40.00	\$ 40.00
23	Reverse Sensor / short	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
<u>LABOUR</u>				
24	Spray Paint Rear Bumper, Bootlip, Inner Panel and Fender	1	\$ 800.00	\$ 800.00
25	Replace & Refit Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
26	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
27	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
28	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-059
DATE : 15-Apr-2020
POLICY NO. : P10351573R00
VEHICLE REG. NO. : SJD57605
VEHICLE MAKE : MITSUBISHI LANCER 1.5 MIVEC GLS 4A/1

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Raymond Tan				Total Labour \$ 2,010.00
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.				Amount Before Excess \$ 6,500.00
Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.				Add GST @ 7% 455.00
Quotation on parts and labour are current and subject to change.				Total Amount Payable \$ 6,955.00

6,625.00#

Repair day - ~~7~~ 4 days.
6

L/S.

After part photo

Sun Pin (LKK)

21/04/2020.

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: