



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101452

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/03/2021
Reference CC6/CTI20005243/Qpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJD 5760S
Insured Veh. SMH 887L
Claim No. SNM20D201780/C02
Policy No. DMPCSNW0002132000
Accident Date 15/04/2020
Inspection Date 21/04/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20005243/Qpa3q2 Date: 09/03/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMH 887L	Veh. Inspected	SJD 5760S	
Policy No.	DMPCSNW0002132000	Coverage (\$)	0.00	
Claim No.	SNM20D201780/C02	Excess (\$)	0.00	
Assign From		Assign Date	21/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER 1.5 MIVEC		c.c	1499
Engine No.	HIDDEN		Year of Reg.	2008
Chassis No.	JMYSRCY2A8U004252		Colour	BLUE
Odometer	267468 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	6 mm	
L/H Front Tyre	205/55 R16	TOYO	6 mm	
R/H Rear Tyre	205/55 R16	TOYO	6 mm	
L/H Rear Tyre	205/55 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/04/2020	Inspection Date	21/04/2020	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 5760S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED	700.00	700.00
10	REAR BUMPER CLIP @ \$5.00	NECESSARY	50.00	30.00
1	REAR BUMPER RETAINER RH	SERVICEABLE	45.00	-
1	REAR BUMPER RETAINER LH	BROKEN	45.00	45.00
1	REAR BUMPER REFLECTOR LH	BROKEN	60.00	60.00
1	REAR TAIL LAMP LH	CRACKED	420.00	360.00
1	REAR TAIL LAMP GROMMET UPPER	NECESSARY	10.00	10.00
1	REAR TAIL LAMP GROMMET LOWER	NECESSARY	10.00	10.00
1	REAR BOOTLID	TO REPAIR SEE LABOUR	700.00	-
1	REAR BOOTLID LOCK	SERVICEABLE	80.00	-
1	REAR BOOTLID HINGE RH	SERVICEABLE	50.00	-
1	REAR BOOTLID HINGE LH	SERVICEABLE	50.00	-
1	REAR BOOTLID SEAL	SERVICEABLE	180.00	-
1	REAR MITSUBISHI EMBLEM	NECESSARY	60.00	60.00
1	REAR LANCER EMBLEM	NECESSARY	60.00	60.00
1	REAR EX EMBLEM	NECESSARY	60.00	60.00
1	REAR MIVEC EMBLEM	NECESSARY	60.00	60.00
1	REAR REINFORCEMENT	BENT	360.00	360.00
1	END PANEL	DENTED	420.00	420.00
1	END PANEL GARNISH	CRUSHED	180.00	180.00
1	REAR SPARE TIRE SINK / PANEL	TO REPAIR SEE LABOUR	650.00	-
1	REAR BUMPER CENTER BRACKET (ADDITIONAL)	BENT	125.00	125.00
	LESS 20% DISCOUNT		-	-508.00
			4,375.00	2,032.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR LICENCE PLATE WITH CASING (SN)	CRUSHED	40.00	40.00
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			240.00	240.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	SPRAY PAINT REAR BUMPER, BOOTLID, INNER PANEL AND FENDER.		800.00	800.00
	REPLACE & REFIT AFFECTED ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID AND REAR SPARE TIRE SINK / PANEL.		1,000.00	900.00
	APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.		100.00	40.00
	REMOVE AND REFIT REAR REVERSE SENSOR.		80.00	30.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			2,010.00	1,800.00
	GRAND TOTAL		6,625.00	4,072.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,250.00
---	--	--	-----------------

Report Ref No. CC6/CTI20005243/Qpa3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJD 5760S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJD 5760S

RE-INSPECTION

