

# ARC

Automotive Repair Centre Pte Ltd  
CO. Reg. No. : 201312913C

## Estimate

38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-059  
DATE : 15-Apr-2020  
POLICY NO. : P10351573R00  
VEHICLE REG. NO. : SJD57605  
VEHICLE MAKE : MITSUBISHI LANCER 1.5 MIVEC GLS 4A/1

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

### ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Bumper / PD.	1	\$ 700.00	\$ 700.00
2	Rear Bumper Clip / NEC	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <del>W</del> ? X SVC	1	\$ 45.00	\$ 45.00
4	Rear Bumper Retainer LH / BR	1	\$ 45.00	\$ 45.00
5	Rear Bumper Reflector LH / BR	1	\$ 60.00	\$ 60.00
6	Rear Tail Lamp LH ? / CRA	1	\$ 420.00	\$ 420.00
7	Rear Tail Lamp Grommet Upper ? / NEC	1	\$ 10.00	\$ 10.00
8	Rear Tail Lamp Grommet Lower ? / NEC	1	\$ 10.00	\$ 10.00
9	Rear Bootlid X R	1	\$ 700.00	\$ 700.00
10	Rear Bootlid Lock X SVC	1	\$ 80.00	\$ 80.00
11	Rear Bootlid Hinge RH X SVC	1	\$ 50.00	\$ 50.00
12	Rear Bootlid Hinge LH X SVC	1	\$ 50.00	\$ 50.00
13	Rear Bootlid Seal ? X SVC	1	\$ 180.00	\$ 180.00
14	Rear Mitsubishi Emblem / NEC	1	\$ 60.00	\$ 60.00
15	Rear Lancer Emblem / NEC	1	\$ 60.00	\$ 60.00
16	Rear EX Emblem / NEC	1	\$ 60.00	\$ 60.00
17	Rear Mivec Emblem / NEC.	1	\$ 60.00	\$ 60.00
18	Rear Reinforcement / BT	1	\$ 360.00	\$ 360.00
19	End Panel ? / PD	1	\$ 420.00	\$ 420.00
20	End Panel Garnish ? / CRA	1	\$ 180.00	\$ 180.00
21	Rear Spare Tire Sink/ Panel ? X R	1	\$ 650.00	\$ 650.00
Total Spare Parts				\$ 4,250.00
<u>SPECIAL NETT</u>				
22	Rear License Plate with Casing / CRA	1	\$ 40.00	\$ 40.00
23	Reverse Sensor / short	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
<u>LABOUR</u>				
24	Spray Paint Rear Bumper, Bootlip, Inner Panel and Fender	1	\$ 800.00	\$ 800.00
25	Replace & Refit Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
26	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
27	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
28	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00

photo -

2415  
125 - 541  
2,540

240

800  
600  
600 900  
40

30

1,800

# ARC

Automotive Repair Centre Pte Ltd  
CO. Reg. No. : 201312913C

## Estimate

38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-059  
DATE : 15-Apr-2020  
POLICY NO. : P10351573R00  
VEHICLE REG. NO. : SJD57605  
VEHICLE MAKE : MITSUBISHI LANCER 1.5 MIVEC GLS 4A/1

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

### ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Estimate prepared by: Raymond Tan				
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.				
Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.				
Quotation on parts and labour are current and subject to change.				
Total Labour			\$	2,010.00
Amount Before Excess			\$	6,500.00
Add GST @ 7%				455.00
Total Amount Payable			\$	6,955.00

Repair day - ~~7~~ 6 days.

L/S.

After paint p photo

Sun Pin (LKK)

21/04/2020.

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

**Supplementary  
Estimate**

ESTIMATE NO. : EST2004-059 (SUP)

DATE : 22-Apr-2020

POLICY NO. : P10351573R00

VEHICLE REG. NO. : SJD5760S

VEHICLE MAKE : MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper Center Bracket <i>BT</i>	1	\$ 125.00	\$ 125.00
Total Spare Parts				\$ 125.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
Total Labour				\$ -
Amount Before Excess				\$ 125.00
Add GST @ 7%				8.75
Total Amount Payable				\$ 133.75

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

$$\begin{array}{r}
 2,540 \\
 - 20\% \\
 \hline
 P = 2,032 \\
 N = 240 \\
 L = 1,800 \\
 \hline
 4,072 \\
 - 20\% \\
 \hline
 3,257.6
 \end{array}$$

4/5  
\$ 3,250  
6 days