



38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-059
DATE : 15-Apr-2020
POLICY NO. : P10351573R00
VEHICLE REG. NO. : **SJD5760S**
VEHICLE MAKE : MITSUBISHI LANCER 1.5 MIVEC GLS 4A/7

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 700.00	\$ 700.00
2	Rear Bumper Clip	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 45.00	\$ 45.00
4	Rear Bumper Retainer LH	1	\$ 45.00	\$ 45.00
5	Rear Bumper Reflector LH	1	\$ 55.00	\$ 55.00
6	Rear Tail Lamp LH	1	\$ 420.00	\$ 420.00
7	Rear Tail Lamp Grommet Upper	1	\$ 10.00	\$ 10.00
8	Rear Tail Lamp Grommet Lower	1	\$ 5.00	\$ 5.00
9	Rear Bootlid	1	\$ 700.00	\$ 700.00
10	Rear Bootlid Number Plate Garnish	1	\$ 160.00	\$ 160.00
11	Rear Bootlid Lock	1	\$ 80.00	\$ 80.00
12	Rear Bootlid Hinge RH	1	\$ 50.00	\$ 50.00
13	Rear Bootlid Hinge LH	1	\$ 50.00	\$ 50.00
14	Rear Bootlid Seal	1	\$ 180.00	\$ 180.00
15	Rear Mitsubishi Emblem	1	\$ 60.00	\$ 60.00
16	Rear Lancer Emblem	1	\$ 60.00	\$ 60.00
17	Rear EX Emblem	1	\$ 60.00	\$ 60.00
18	Rear Mivec Emblem	1	\$ 60.00	\$ 60.00
19	Rear Reinforcement	1	\$ 360.00	\$ 360.00
20	End Panel	1	\$ 420.00	\$ 420.00
21	End Panel Garnish	1	\$ 180.00	\$ 180.00
22	Rear Spare Tire Sink	1	\$ 650.00	\$ 650.00
Total Spare Parts				\$ 4,400.00
	<u>SPECIAL NETT</u>			
23	Rear License Plate with Casing	1	\$ 40.00	\$ 40.00
24	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 240.00
	<u>LABOUR</u>			
25	Spray Paint Rear Bumper, Bootlip and Inner Panel include	1	\$ 800.00	\$ 800.00
	Blending Fender LH			
26	Replace & Refit Affected Accident Parts	1	\$ 1,000.00	\$ 1,000.00
27	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2004-059
DATE : 15-Apr-2020
POLICY NO. : P10351573R00
VEHICLE REG. NO. : **SJD5760S**
VEHICLE MAKE : MITSUBISHI LANCER 1.5 MIVEC GLS 4A/7

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
28	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
29	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,010.00
Amount Before Excess	\$ 6,650.00
Add GST @ 7%	465.50
Total Amount Payable	\$ 7,115.50