



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

C7PI

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

16-04-2020

TP China.
Ashes.

Accident date: 15/04/2020

Estimated repair cost for vehicle no: SLD864K TOYOTA COROLLA ALTIS 1.6 A '16

CHASSIS: MR053REH104546666

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$685.80	✓
2	2	Rear Boot Lid Hinge <i>the new</i>	\$77.80	\$155.60	+
3	1	Rear Boot Lid Emblem Logo <i>the new</i>		\$66.70	✓
4	1	Rear Boot Lid Lock <i>Damaged.</i>		\$382.00	✓
5	1	Rear Boot Lid Weatherstrip <i>at</i>		\$166.40	✓
6	1	Rear Boot Lid Reverse Camera <i>Not the new</i>		\$450.00	✓
7	1	Rear Boot Lid Number Plate <i>the new</i>		\$50.00	+
8	1	Rear Boot Lid Center Moulding <i>at</i>		\$307.90	✓
9	2	Rear Boot Lid Side Reflector <i>at</i>	\$280.50	\$561.00	✓
10	1	Rear Bumper <i>Debond</i>		\$482.00	✓
11	10	Rear Bumper Clip <i>the new</i>	\$6.50	\$65.00	30
12	2	Rear Bumper Side Retainer <i>the new</i>	\$104.40	\$208.80	✓
13	2	Rear Bumper Side Reflector <i>the new</i>	\$35.10	\$70.20	+
14	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00	200/50
15	1	Rear Bumper Reinforcement <i>Best.</i>		\$381.70	✓
16	2	Rear Fender Inner Trim Board <i>2x1</i>	\$415.10	\$830.20	+
17	16	Rear Fender Inner Trim Board Clip <i>the new</i>	\$6.50	\$104.00	+
18	1	Rear End Panel <i>Dented.</i>		\$581.10	✓
19	1	Rear End Panel Top Garnish <i>Dented</i>		\$229.40	✓
20	1	Rear Spare Tyre Panel Top Cover <i>Debond</i>		329.00	✓
21	1	Rear Spare Tyre Panel Sealant <i>3x1</i>		\$450.00	+
22	1	Rear Exhaust		\$781.10	+
23	1 set	TRD Bodykit (Special Nett) <i>Debond.</i>		\$3,500.00	900/50
		Rear End Panel Antenna Sensor <i>Cracked</i>		98.50	✓
Subtotal :-				\$10,861.90	

450730

338047

S.N. 1100

SLD 86410

Labour charges

To remove & refit cushion & trim board	\$280.00 60
To remove & refit rear reverse sensor	\$100.00 50
To remove & refit reverse camera	\$180.00 50
To remove & refit rear exhaust	\$280.00 X
To check wiring	\$100.00 30
Tuff kote	\$150.00 60
Towing fee	2150 \$150.00 X
Panel beating	\$1,500.00 900.
Spray painting	\$1,200.00 1000.

Subtotal :- \$3,940.00

Total:- \$14,801.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
1/2 16/04/20

total 6630.47

H/S: 5.31c.

06 Days.

5.31c.