

ASS. REC. BY:

REF:

FCZ/ 2000 5250/Kpa392

C

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

1-B1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S110 5158

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Pnw

c.c

1798

Colour

M.P. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

152793

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B31F4103078574

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Positun

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

14/4/20

D.O.I.

16/4/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8 4250.83

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

CLOSE: 15/7/2020

Not Authored  
Recovery B4 paint

84250.83 AAD2004-063

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5158E**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 APR 2020

**SHD 5158E**

JTDKB3FU103078574

TOYOTA

PRIUS

14.4.2020

**FCIL**

19/12/2018

PART		LIST	
1	REAR BUMPER	\$ Bu	442.60 ✓
1	REAR BUMPER RE-INFORCEMENT	\$ B	332.70 ✓
1	REAR BUMPER TOWING COVER	\$ D	15.40 ✓
1	GUARD, REAR BUMPER, CENTER	\$ CM	576.30 ✓
1	REAR BUMPER SIDE RETAINER LH	\$ S	116.50 X
1	REAR BUMPER SIDE RETAINER RH	\$ D	117.70 ✓
1	ANTENNA, ELECTRICAL KEY	\$ S	72.00 X
1	REAR TAILGATE	\$ R	1,147.80 X
1	REAR TAILGATE OUTER GARNISH	\$ S	925.60 X
1	REAR TAILGATE WEATHERSTRIP	\$ S	372.30 X
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$ S	467.00 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$ S	650.30 X
1	TAILLAMP LOWER RH	\$ CM	502.00 ✓
1	TAILLAMP UPPER RH	\$ S	451.80 X
1	REAR BUMPER SIDE RH	\$ mgcm	123.70 ✓
1	REAR BUMPER SIDE LH	\$ S	123.70 X
1	TAILLAMP LOWER LH	\$ S	502.00 X
1	TAILLAMP UPPER LH	\$ S	443.30 X
1	COVER, DECK TRIM, REAR	\$ S	126.70 X
1	COVER, FLOOR UNDER, NO 1	\$ S	175.10 X
1	COVER, FLOOR UNDER, NO 2	\$ S	241.90 X
1	COVER, REAR FLOOR	\$ D	229.90 ✓
1	PANEL SUB-ASSY, QUARTER, RH	\$ R	871.50 X
1	REAR FENDER LINER	\$ S	139.80 X
1	DUCT ASSY, QUARTER VENT, RH	\$ S	67.00 X
1	SEAL, REAR BUMPER SIDE, RH	\$ S	88.50 X

**Trans-cab Auto Services Pte Ltd****AAD2004-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5158E**

1	PAN, REAR FLOOR	\$	<i>11</i>	583.40	X
1	PIPE ASSY, EXHAUST, TAIL	\$	<i>B</i>	1,655.40	✓
1	BRACKET, EXHAUST PIPE SUPPORT, NO.5	\$	<i>P<sub>L</sub></i>	41.80	X
1	SUPPORT, EXHAUST PIPE, NO.4	\$	<i>S<sub>L</sub></i>	49.10	X
1	SUPPORT, EXHAUST PIPE, NO.5	\$	<i>S<sub>L</sub></i>	49.10	X
1	GASKET, EXHAUST PIPE	\$	<i>P<sub>L</sub></i>	53.50	X
1	PIPE ASSY, EXHAUST, FRONT	\$	<i>11</i>	2,927.20	} X
1	INSULATOR, MAIN MUFFLER HEAT, RH	\$	<i>P<sub>L</sub></i>	141.00	
1	WIRE, BACK DOOR, NO.2	\$	<i>S<sub>L</sub></i>	294.40	
1	WIRE, LUGGAGE ROOM, NO.3	\$	<i>S<sub>L</sub></i>	170.70	
1	ARM ASSY, TRAILING, REAR RH	\$	<i>S<sub>L</sub></i>	370.40	
1	ARM ASSY, REAR SUSPENSION, NO.1 RH	\$	<i>S<sub>L</sub></i>	239.20	
1	ARM ASSY, REAR SUSPENSION, NO.2 RH	\$	<i>S<sub>L</sub></i>	497.50	
1	ARM ASSY, UPPER CONTROL, REAR RH	\$	<i>S<sub>L</sub></i>	420.80	
1	CARRIER SUB-ASSY, REAR AXLE, RH	\$	<i>S<sub>L</sub></i>	953.60	
1	ABSORBER ASSY, SHOCK, REAR RH	\$	<i>P<sub>L</sub></i>	127.00	
1	HUB & BEARING ASSY, REAR AXLE, RH	\$	<i>P<sub>L</sub></i>	725.60	
1	SUPPORT ASSY, REAR SUSPENSION, RH	\$	<i>S<sub>L</sub></i>	149.30	
1	MEMBER SUB ASSY, REAR SUSPENSION	\$	<i>S<sub>L</sub></i>	2,245.20	
<b>TOTAL</b>		\$		<b>21,017.30</b>	
<b>25%</b>		\$		<b>5,254.33</b>	
		\$		<b>15,762.98</b>	

**Special Nett**

1SET	PARKING AID	\$	<i>Shan</i>	700.00	<i>2205m</i>
1SET	REAR BUMPER CLIP	\$	<i>me</i>	68.00	—
1	REAR TAILGATE TOYOTA LOGO	\$	<i>me</i>	47.00	—
1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>me</i>	52.90	—
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>me</i>	53.50	—
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>me</i>	80.00	<i>305m</i>
1	REAR TAILGATE STICKER '6555-3333'	\$	<i>me</i>	80.00	<i>305m</i>
1	REAR BUMPER PROTECTOR	\$	<i>me</i>	120.00	<i>305m</i>
1	WHEEL, RIM	\$	<i>S<sub>L</sub></i>	1,879.40	X
1	TYRE 195/65/15	\$	<i>S<sub>L</sub></i>	350.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5158E****AAD2004-063**

1 WHEEL RIM COVER	\$	211.50	}	X
1 REAR RH BUMPER RETAINER CLIP	\$	38.00		
1 REAR LH BUMPER RETAINER CLIP	\$	38.00		
1SET TAILLAMP LOWER CLIP	\$	35.00		
1SET TAILLAMP UPPER CLIP	\$	35.00		
2 REAR WINDSCREEN SEALANT	\$	120.00		
1 WINDSCREEN MOULDING	\$	180.00		
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	120.00		
1SET REAR FENDER LINER CLIP	\$	35.00		
2 REAR END PANEL SEAM SEALANT	\$	170.00		
1SET EXHAUST BOLT, SPRING AND NUTS	\$	35.00		
<b>TOTAL</b>	<b>\$</b>	<b>4,448.30</b>		

<b>TOTAL PARTS</b>	<b>\$</b>	<b>20,211.28</b>
--------------------	-----------	------------------

**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5158E****AAD2004-063**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	nn	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		7,500.00	6001
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	4	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To supply and re-do rear luggage floor panel insulation padding.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		7,500.00	4001
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	4	170.00	X
Towing Fees	\$	4	150.00	X
To transfer of Rear Luggage Floor Panel fittings, attachments and perform water seepage test.	\$	4	380.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5158E****AAD2004-063**

To drop rear exhaust box, renew the same, to repair and  
realign centre exhaust pipe.

\$ 170.00

To repair and realign rear exhaust pipe.

\$ 170.00

To pull and jack out vehicle body panel and correct it to  
symmetrical position with the aid of hydraulic pneumatic  
jack.

\$ ~ 380.00 X

To perform a comprehensive vehicle diagnostic test and  
reset vehicle warning indicators.

\$ ~ 380.00 X

**TOTAL \$ 20,660.00****Over All Total \$ 40,871.28****(PART-BY-PART) Repair Days****25 Days****3 days**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD5158E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Apr 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B92468
Chassis No.:	JTDKB3FU103078574
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	19 Dec 2018
First Registration Date:	19 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2026
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,645.00
<b>Total Rebate Amount:</b>	<b>\$28,330.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Apr 2020

OK