

Not Authored
Resurvey B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5158E

AAD2004-063

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 APR 2020

SHD 5158E

JTDKB3FU103078574

TOYOTA

PRIUS

14.4.2020

FCIL

19/12/2018

PART		LIST	
1	REAR BUMPER	\$	Bu 442.60 ✓
1	REAR BUMPER RE-INFORCEMENT	\$	Bu 332.70 ✓
1	REAR BUMPER TOWING COVER	\$	Bu 15.40 ✓
1	GUARD, REAR BUMPER, CENTER	\$	CM 576.30 ✓
1	REAR BUMPER SIDE RETAINER LH	\$	Sm 116.50 X
1	REAR BUMPER SIDE RETAINER RH	\$	Orv 117.70 ✓
1	ANTENNA, ELECTRICAL KEY	\$	Sm 72.00 X
1	REAR TAILGATE	\$	R 1,147.80 X
1	REAR TAILGATE OUTER GARNISH	\$	Sm 925.60 X
1	REAR TAILGATE WEATHERSTRIP	\$	Sm 372.30 X
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	Sm 467.00 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	Sm 650.30 X
1	TAILLAMP LOWER RH	\$	CM 502.00 ✓
1	TAILLAMP UPPER RH	\$	Sm 451.80 X
1	REAR BUMPER SIDE RH	\$	mgcm 123.70 ✓
1	REAR BUMPER SIDE LH	\$	Sm 123.70 X
1	TAILLAMP LOWER LH	\$	Sm 502.00 X
1	TAILLAMP UPPER LH	\$	Sm 443.30 X
1	COVER, DECK TRIM, REAR	\$	Sm 126.70 X
1	COVER, FLOOR UNDER, NO 1	\$	Sm 175.10 X
1	COVER, FLOOR UNDER, NO 2	\$	Sm 241.90 X
1	COVER, REAR FLOOR	\$	Orv 229.90 ✓
1	PANEL SUB-ASSY, QUARTER, RH	\$	R 871.50 X
1	REAR FENDER LINER	\$	Sm 139.80 X
1	DUCT ASSY, QUARTER VENT, RH	\$	Sm 67.00 X
1	SEAL, REAR BUMPER SIDE, RH	\$	Sm 88.50 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5158E**AAD2004-063**

1	PAN, REAR FLOOR	\$	11	583.40	X
1	PIPE ASSY, EXHAUST, TAIL	\$	11	1,655.40	✓
1	BRACKET, EXHAUST PIPE SUPPORT, NO.5	\$	11	41.80	X
1	SUPPORT, EXHAUST PIPE, NO.4	\$	11	49.10	X
1	SUPPORT, EXHAUST PIPE, NO.5	\$	11	49.10	X
1	GASKET, EXHAUST PIPE	\$	11	53.50	X
1	PIPE ASSY, EXHAUST, FRONT	\$	11	2,927.20	} X
1	INSULATOR, MAIN MUFFLER HEAT, RH	\$	11	141.00	
1	WIRE, BACK DOOR, NO.2	\$	11	294.40	
1	WIRE, LUGGAGE ROOM, NO.3	\$	11	170.70	
1	ARM ASSY, TRAILING, REAR RH	\$	11	370.40	
1	ARM ASSY, REAR SUSPENSION, NO.1 RH	\$	11	239.20	
1	ARM ASSY, REAR SUSPENSION, NO.2 RH	\$	11	497.50	
1	ARM ASSY, UPPER CONTROL, REAR RH	\$	11	420.80	
1	CARRIER SUB-ASSY, REAR AXLE, RH	\$	11	953.60	
1	ABSORBER ASSY, SHOCK, REAR RH	\$	11	127.00	
1	HUB & BEARING ASSY, REAR AXLE, RH	\$	11	725.60	
1	SUPPORT ASSY, REAR SUSPENSION, RH	\$	11	149.30	
1	MEMBER SUB ASSY, REAR SUSPENSION	\$	11	2,245.20	
TOTAL		\$		21,017.30	
25%		\$		5,254.33	
		\$		15,762.98	

Special Nett

1SET	PARKING AID	\$	Shan	700.00	220111
1SET	REAR BUMPER CLIP	\$	11	68.00	—
1	REAR TAILGATE TOYOTA LOGO	\$	11	47.00	—
1	REAR TAILGATE WORDING 'PRIUS'	\$	11	52.90	—
1	REAR TAILGATE WORDING 'HYBRID'	\$	11	53.50	—
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	11	80.00	301111
1	REAR TAILGATE STICKER '6555-3333'	\$	11	80.00	301111
1	REAR BUMPER PROTECTOR	\$	11	120.00	301111
1	WHEEL, RIM	\$	11	1,879.40	X
1	TYRE 195/65/15	\$	11	350.00	X

Trans-cab Auto Services Pte Ltd

AAD2004-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5158E

1	WHEEL RIM COVER	\$	211.50	}	X
1	REAR RH BUMPER RETAINER CLIP	\$	38.00		
1	REAR LH BUMPER RETAINER CLIP	\$	38.00		
1SET	TAILLAMP LOWER CLIP	\$	35.00		
1SET	TAILLAMP UPPER CLIP	\$	35.00		
2	REAR WINDSCREEN SEALANT	\$	120.00		
1	WINDSCREEN MOULDING	\$	180.00		
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	120.00		
1SET	REAR FENDER LINER CLIP	\$	35.00		
2	REAR END PANEL SEAM SEALANT	\$	170.00		
1SET	EXHAUST BOLT, SPRING AND NUTS	\$	35.00		
TOTAL		\$	4,448.30		
TOTAL PARTS		\$	20,211.28		

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD2004-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5158E

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	nn	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		7,500.00	6001
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	4	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	201
To supply and re-do rear luggage floor panel insulation padding.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		7,500.00	6001
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	4	170.00	X
Towing Fees	\$	4	150.00	X
To transfer of Rear Luggage Floor Panel fittings, attachments and perform water seepage test.	\$	4	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5158E**AAD2004-063**

To drop rear exhaust box, renew the same, to repair and
realign centre exhaust pipe.

\$ 170.00

To repair and realign rear exhaust pipe.

\$ 170.00

} 661

To pull and jack out vehicle body panel and correct it to
symmetrical position with the aid of hydraulic pneumatic
jack.

\$ ~ 380.00 X

To perform a comprehensive vehicle diagnostic test and
reset vehicle warning indicators.

\$ ~ 380.00 X

TOTAL \$ **20,660.00****Over All Total** \$ **40,871.28****(PART-BY-PART) Repair Days****25 Days****3 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: