

16/04/2020

1st



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SLU 3131HMake & Model : HONDA CIVIC 1.6 VTI CVTYear of Manufacture : 2017Chassis No. : MRHFC5650GT001458Ins Company : INDIA INT'L INS

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 11.04.2020Time of Accident : 1.20PMSuggested Days of Repair : 7

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Contact No

Parts (a) Cost / List Price Items \$ 8,551.20Plus/Less 20% \$ 1,710.24Total of Cost / List \$ 6,840.96

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 60.00Total Parts Cost (Appendix A) \$ 6,900.96Labour (Appendix B) \$ 4,650.00Total Repair Cost \$ 11,550.9668485725 - JOHARI
68485726 - TINIE

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Steve (LKK) 83728813

Company : _____

Survey conducted on : 20/4/20 at 11.35 am

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL : 68438723/68438736 Fax: 67436072

Spare Parts

Vehicle No : SLU 3131H

Make & Model : HONDA CIVIC 1.6 VYI CVT

Chassis No : MRHFC5650GT001458

Sales Order : _____

Order By : _____

Case Owner : _____

Year Manufacture : 2017

Engine No : _____

Supplier : _____

Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	LHR DOOR X R	1		\$1,110.84		
2	LHR DOOR RUBBER X NN	1		\$ 115.68		
3	LHR DOOR HANDLE X NN	1		\$ 130.32		
4	LHR DOOR HANDLE KNOB X NN	1		\$ 52.44		
5	LHR DOOR LOCK X NN	1		\$ 95.76		
6	LHR DOOR HINGE TOP X NN	1		\$ 45.48		
7	LHR DOOR HINGE BOTTOM X NN	1		\$ 45.48		
8	LHR DOOR CHECKER X NN	1		\$ 54.00		
9	LHR FENDER / OK	1		\$ 853.92		
10	LHR FENDER QUATOR GLASS WITH CHROME / MK1	1		\$ 163.92		
11	LHR FENDER COWLING / CR4	1		\$ 75.60		
12	LHR FENDER COWLING CLIPS / MK	8		\$ 33.60	20	
13	LHR PETROL COVER (OUTER) X NN	1		\$ 128.04		
14	LHR PETROL COVER RUBBER (INNER) X NN	1		\$ 73.56		
15	LHR PETROL TANK ASSY WITH RUBBER TUBE X 1 NN	1		\$ 798.48		
16	LHR TAIL LAMP / OK	1		\$ 337.20		
17	REAR BOOT X R	1		\$ 638.16		
18	REAR BOOT HINGE LH X NN	1		\$ 53.76		
19	REAR BOOT HINGE COVER LH X NN	1		\$ 18.48		
20	REAR BOOT RUBBER X NN	1		\$ 84.00		
21	REAR BOOT LAMP LH / OK	1		\$ 146.76		
22	REAR BOOT CENTRE GARNISH X NN	1		\$ 133.08		
23	REAR BOOT EMBLEM X NN	1		\$ 14.28		
24	CIVIC WORDING X NN	1		\$ 13.80		
25	1-VTEC WORDING X NN	1		\$ 12.60		
26	REAR BUMPER / OK	1		\$ 556.44		
27	REAR BUMPER CLIPS / MK	15		\$ 63.00	30	
28	REAR BUMPER SIDE RETAINER LH / OK	1		\$ 13.80		
29	REAR BUMPER BRACKET (UNDER TAIL LAMP) ?	1		\$ 10.20		
30	REAR BUMPER REFELECTOR LAMP CVR LH / CV1	1		\$ 21.36		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.