



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : QBE Insurance (Singapore) Pte Ltd
 1 Raffles Quay
 #29-01 South Tower
 Singapore 048583

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 21/01/2020
 TP Veh Reg No: YN7347J

RASUL
Up 900/0068
3 days
L/S
14/05/2020
@ 1500

Resury after repair

Estimate No: ES2000037
 Date: 02 Apr 2020
 Policy No:
 Veh Reg No: XD5366G
 Make/Model: MITSUBISHI
 FP51JDR4RDEA
 Chassis No: FP51JDA00890
 Engine No: 6M70450126
 Reg. Date: 07/03/2012

Estimate Repair Cost to Vehicle No :XD5366G

Description	U/Price	Quantity	List Price SS	Amount SS
Spare Parts				
1 CORNER STEP GARNISH <i>scr -</i>	255.00	1 PC	255.00	
2 CORNER FAIRING - LH <i>scr -</i>	580.00	1 PC	580.00	7695
3 CORNER INNER SHIELD - LH <i>scr -</i>	360.00	1 PC	360.00	
4 REAR SIDE FENDER - LH <i>x scr</i>	850.00	1 PC	850.00 X	258
5 DIESEL TANK <i>bt -</i>	2,200.00	1 PC	2,200.00	
6 EXHAUST CATALYTIC CONVERTOR <i>bt -</i>	2,800.00	1 PC	2,800.00	5771.25
7 EXHAUST CATALYTIC CONVERTOR COVER <i>bt -</i>	1,500.00	1 PC	1,500.00	
8 RADIATOR SPRAY TANK <i>x scr</i>	240.00	1 PC	240.00 X	
9 FRONT TYRE - LH <i>x scr</i>	800.00	1 PC	800.00 X	
			9,585.00	9,585.00
Labour				
10 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00 <i>600</i>	
11 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00 <i>200</i>	
12 TO REPLACE TYRE	380.00	1 JOB	380.00 <i>xm</i>	
13 TO CHECK WIRING FUNCTIONS.	200.00	1 JOB	200.00 <i>50</i>	
14 TO REMOVE & REPLACE FUEL TANK	250.00	1 JOB	250.00 <i>xm</i>	
			3,030.00	3,030.00
			Total	SS 12,615.00
			Add GST @ 7%	883.05
			Total Amount Payable	SS 13,498.05

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FOUR HUNDRED NINETY EIGHT AND CENTS FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

For Yee Auto Pte Ltd

[Handwritten Signature]
 AUTHORISED SIGNATURE



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile 9687 4031
 Email yeeautopteLtd@gmail.com
 Registration No: 201719251W GST No: 201719251W

M/S : QBE Insurance (Singapore) Pte Ltd
 1 Raffles Quay
 #29-01 South Tower
 Singapore 048583

Estimate No: **ES2000037**
 Date: 15 May 2020
 Policy No:
 Veh Reg No: **XD5366G**
 Make/Model: MITSUBISHI
 FP51JDR4RDEA
 Chassis No: FP51JDA00890
 Engine No: 6M70450126
 Reg. Date: 07/03/2012

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 21/01/2020
 TP Veh Reg No: YN7347J

Estimate Repair Cost to Vehicle No :XD5366G

Description	U/Price	Quantity	List Price SS	Amount SS
Supplementary Parts to Repair				
Spare Parts				
1 ADBLUE TANK <i>bt</i> ADBLUE	4,500.00	1 PC	4,500.00	4,500.00
Labour	1,200.00	1 JOB	1,200.00 <i>200</i>	1,200.00
2 TO REMOVE & REPLACE ADBLUE TANK , EXHAUST CATALYTIC CONVETOR.			1,200.00	1,200.00
			Total	SS 5,700.00
			GST Amount	SS 399.00
			Total Amount Payable	SS 6,099.00


5771.25
850.00
3375.00
200.00

10,196.25
20%
8157

45-8150

3 days

For Yee Auto Pte Ltd


 AUTHORIZED SIGNATURE