

ASSIGNED BY Taufik REF: NS/INC 20005258/TIVf3

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop ins _____
 of _____
 Insured FBR 1964T
 Policy No 5116802115
 Claims No MT/1091440-002
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball or Market Value: _____
 DAD Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 LUT 8.11: _____ % 3 Vol.: Yes or No
 CA / REV / REP. / 24 HRS
 Date _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD4769Z Yr Regn: 2013 / July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai 140 cc 1685
 Colour Blue A/C: Insured / Std / NI / NA
 Sp. Reading 955741 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHLB41UMD4 038777
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SR / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Flankook
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/4/20 D.O.I. 16/4/20
 Survey held at Comfort Layan
 Des. of Damages: Frt / Rear / O/S / NI/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

20/4/20 Taufik confirmed LS \$2300 by email (Red 30H-90, 579) TP INC: FBR 1964T

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) 21/4 - typist

Rep. Form: TP

Lump Sum / F.B.I. 2300/7

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

\$ + \$ = \$

Fuel

Others

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Monday, 20 April 2020 4:23 PM
To: Veron Chen (LKKAUTO)
Subject: RE: REQUEST FOR CLAIM NUMBER

Hi

Claim created.

Azlin Rani
Senior Administrator
Operations, Motor & Personal Lines



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 20 April 2020 12:54 PM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

[CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you can confirm the sender and know the content is safe.]

Dear Sir/Madam,

Kindly provides claim number

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1091440 - 002	COMFORT TRANSPORTATION PTE LTD	SHD 4769Z	FBR 1964T

D.O.A	Time of Accident	Estimate	Tentative repair cost
15.4.2020	15:50	\$5,317.90	\$2,300.00

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUC-4S
LKK - Taufik

Date: 16.04.2020

Time: 10:06:06

Page: 1/2

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305393358
 REGN NO : SHD4769Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : i-40
 DATE OF REGN : 31.07.2013
 DATE/TIME IN : 15.04.2020 16:50
 ACCIDENT DATE : 15.04.2020

JOB PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0593-U	FRT DOOR LH	1	2,256.40	20.00	1,805.12	dl-
0002 04-01-0103-0596-U	REAR DOOR LH	1	2,201.10	20.00	1,760.88	Ry
0003 04-01-0103-0813-G	ROCKER PANEL GARNISH LH	1	403.00	20.00	322.40	Ly
0004 28-01-0103-0003-A	Frt Door COMFORTDELGRO LH	1	75.00	10.00	67.50	an-
0005 28-01-9999-2023-A	Rear Door APPS LH	1	80.00	10.00	72.00	an-

SUB-TOTAL : 4,027.90

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	750.00	600
0002 L	TRANSFER OF DOORS	240.00	60

SUB-TOTAL : 1,290.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK - Taufik

NTUC-45

Date: 16.04.2020

Time: 10:06:06

Page: 2/2

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS : COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO : 305393358
REGN NO : SHD4769Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 31.07.2013
DATE/TIME IN : 15.04.2020 16:50
ACCIDENT DATE : 15.04.2020

JOB PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,317.90

Lump

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary damage must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749
- WP' 16/4/2020 335m

Lump sum
Resurvey after repair

03 days
taufik @ Tahan to van
Sur C Ikkanto Gum